

REPORT of SURVEY for REPAIRS.

32273

No. in Reg. Book. 333 No. 1286 Survey held at London Date, first Survey 12 April Last Survey 19 April 1872
 on the "Durham" Master S. Kerr
 Tonnage 1286 built at Gallion When built 1864
 By whom built _____ Owners G. Marshall
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Regents dry dock & E. S. Dock
 Last Survey, No. 31647 Port Lon. Classed B.A. 5 R.S. No. 170
 (H.T. Lond 71) 5/71

REPAIRS, &c.

Yellow metal sheathing stripped off, resaulted from keel to eighth seam of deck, and resheathed with Yellow Metal on Felt —

This vessel is remarkably well fastened and is now excellent condition —

Present Condition of the

| | | |
|-------------------------------------------|------------------------------------------|----------------------------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the openings | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings <u>Good</u> | Ditto Ditto at other places <u>Good</u> | Condition, how ascertained <u>Suspicious</u> |
| Planksheers <u>where seen</u> | Keelsons | Sails |
| Sheerstrakes | Clamps and Shelves <u>where seen</u> | Anchors No. of |
| Topsides | Ceiling | Cables |
| Wales | Rudder <u>LYM</u> When put on <u>now</u> | Hawsers and Warps |
| Plank (Bottom) and Counter | Caulking of | Standing & Running Rigging |
| Engine Room Skylights | Bottom, Deck, & Waterways <u>good</u> | Hatches <u>good</u> |
| Coal Bunker, Openings, Lids, &c. | Scuppers | Cargo and Main Hatchways |

General Observations and Opinion,

In consequence of the large quantity of work used in the construction of this vessel which has now been examined, I beg respectfully to recommend her claims to the favourable consideration of the Committee

The Amount of Entry Fee.....£ — : — : is received by me, to be raised to 14/6

Special..... 5 : 5 : under the mixed material

Certificate (if required) : 5 : Rule 2

Committee's Minute 25 April 1872

Character assigned

Raise to 14/6
12 + 14/6

Thos. W. Brown