

REPORT of SURVEY for REPAIRS.

32853

No. in Reg. Book. 793 No. 1689 Survey held at London Date, first Survey Augst 6th Last Survey 7th 1872
 on the Ship "Asia" Master J. Moodie Cummings
 Tonnage 2054 built at Glenrock When built 1850
 By whom built Steel Owners Robt & Co
 Port belonging to Port Glasgow Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Simultaneous Dry Dock
 Last Survey, No. 1689 Port Port Classed Red A. 1.
 REPAIRS, &c. now done, SS. 69 - 7 yrs.

Caulked from keel to gunwale and the bottom re-sheathed with Yellow Metal upon Felt. About forty butts of bottom on both sides capped with lead; the scarphs of keel caulked and capped with lead.

Present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>where</u>	Ditto Ditto at other places <u>where</u>	Condition, how ascertained <u>where</u>
Planksheers <u>caulked</u>	Keelsons	Sails
Sheerstrakes <u>"</u>	Clamps and Shelves	Anchors No. of <u>3 B. 1 S. 2 K</u>
Topsides <u>"</u>	Ceiling	Cables
Wales <u>"</u> <u>seen</u>	Rudder <u>seen</u>	Hawsers and Warps <u>seen</u>
Plank (Bottom) and Counter <u>caulked</u>	Copper <u>FeYM</u> When put on <u>now</u>	Standing & Running Rigging
Engine Room Skylights	Caulking of <u>good when</u>	Scuppers <u>efficient</u> Cargo and Main Hatchways <u>efficient</u> Hatches <u>efficient</u>
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>tested</u>	

General Observations and Opinion,

She is now where seen in good and efficient condition, fit in my opinion for the safe conveyance of dry cargoes to and from all parts of the world, and to remain as classed

The Amount of Entry Fee.....£ - - - is received by me,

Special..... 2 : 2 : WMS

Certificate (if required) : 5 : 9/1/72

Committee's Minute 6th September 1872

Character assigned Red A. 1.

J. H. Morrish



©2021

Lloyd's Register Foundation

LON658-0002