

# REPORT of SURVEY for REPAIRS.

32658

No. in **No.** Survey held at London Date, first Survey Oct 3<sup>rd</sup> Last Survey Oct 24<sup>th</sup> 18 72  
 eg. Book. on the 334 3<sup>rd</sup> "Durban" Master Jarvis  
 Tonnage 332 built at London When built 1870  
 By whom built Salisbury Owners Bullard & Co  
 Port belonging to London Destined Voyage Natal  
 If Surveyed Afloat or in Dry Dock Horseferry dry dock & St Katharines Dock  
 Last Survey, No. 32152 Port Lon. Classed 10 A 1  
 2. 72

REPAIRS, &c.

*Stripped recaulked from keel to metal line and the yellow metal renewed on felt.*

Present Condition of the

Decks	} <i>Good where seen</i>	Treenails	} <i>Good where seen</i>	Windlass and Capstan	} <i>Good &amp; sufficient</i>
Waterways		Breasthooks and Stenson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>YM or F</u> When put on <u>now</u>		Standing & Running Rigging	
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways	Hatches <u>good</u>	
Bottom, Deck, & Waterways <u>good</u>					

General Observations and Opinion,

*This vessel is eligible in my opinion to remain as classed 10 A 1*

*Thos. W. Wawn*

The Amount of Entry Fee.....£ - : - : is received by me,

Special..... 1 : 1 : *EL*

Certificate (if required) : : *EL*

Committee's Minute 1<sup>st</sup> November 1872

Character assigned 10 A 1

*record of M*  
*T.W.*



© 2021

Lloyd's Register Foundation

LON658-0073