

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey 4th Oct^r Last Survey Oct^r 24th 1872
on the Barque Naparima Master W. Coleman
20 Tonnage 356 built at Bristol When built 1855
By whom built 347 Owners Scrutton & Co
Port belonging to London Destined Voyage West Indies
If Surveyed Afloat or in Dry Dock Union Dry dock & W. India docks
Last Survey, No. 31937 Port Lon. Classed Cont^d 13. A. 1. 1871

REPAIRS, &c.

Stripped off the Yellow metal sheathing. Hung her in shores Caulked over all. - Deck on Port side nearly all new. also the middle line stuff. Catheads both new. Starb^d. hawse pipe. New hawse timber 'Port side' five new tough tree timbers. two new lengths of tough tree rail. and bulwark berthing at the bow, a length of sheer strake, and three fore hoods all on the Port bow from damage. - twelve Y-metal bolts in the lodging knees renew'd. - Repaired the Windlass.
Resheathed with Yellow metal on felts. -

Present Condition of the

Decks	good	Treenails	good where seen	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	from the Deck
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of	3 B. 1 S. 2 K
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder	efficient	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Gaffer	Set & ymk When put on now	Standing & Running Rigging	"
Engine Room Skylights		Caulking of	good		
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	where tested		
Scuppers	good	Cargo and Main Hatchways	good	Hatches	good

General Observations and Opinion,

She is now in good condition and is in my opinion, entitled to remain as Class'd Cont^d 9. A. 1.
Samuel Presnor

The Amount of Entry Fee.....£ 1 : - : is received by me,
Special..... 1 : 1 :
Certificate (if required) : :
9/12/72.

Committee's Minute 10th December 1872

Character assigned

about 9 A
need repair
JDN



© 2021

Lloyd's Register Foundation

LON658-0111

Napierina



© 2021

Lloyd's Register
Foundation