

# REPORT of SURVEY for REPAIRS.

32941

No. in Reg. Book. **No.** Survey held at London Date, first Survey March 10 Last Survey March 12 18 73  
on the 43<sup>rd</sup> "Clausina" Master R. Rickaby  
Tonnage 461 built at Sunderland When built 1864 - 11 mo  
By whom built \_\_\_\_\_ Owners M. Slanagan  
Port belonging to Sunderland Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock Bullhead dry dock  
Last Survey, No. 10252 Port Sunderland Classed 11 A 1  
REPAIRS, &c. HT Lw 70 12.31

Yellow metal stripped off, recaulked from keel to metal line and the yellow metal sheathing renewed on Felt

## Present Condition of the

Decks	<u>Good</u>	Treenails		Windlass and Capstan	
Waterways	"	Breasthooks and Stemson		Pumps	
Comings	"	Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	<u>Not seen</u>	Condition, how ascertained	
Planksheers	"	Keelsons		Sails	<u>Sufficient</u>
Sheerstrakes	"	Clamps and Shelves		Anchors No. of	
Topsides	"	Ceiling		Cables	
Wales	"	Rudder		Hawsers and Warps	
Plank (Bottom) and Counter	"	Copper <u>I &amp; J M</u> When put on <u>now</u>		Standing & Running Rigging	
Engine Room Skylights		Caulking of		Cargo and Main Hatchways	<u>good</u>
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	<u>when taken good</u>	Hatches	<u>good</u>
General Observations and Opinion,		Scuppers			

This vessel is eligible in my opinion to remain as classed

Thos. W. Wawn

The Amount of Entry Fee.....£ : : is received by me,

Special..... 1 : 1 : } WMA

Certificate (if required) : 5 : } 28/3/73

Committee's Minute 25<sup>th</sup> March 18 73.

Character assigned

11 A 1  
renewed  
T.W.



© 2021

Lloyd's Register Foundation