

33232 *Change of Owners* **REPORT of SURVEY for REPAIRS.**

No. in Reg. Book. **No.** Survey held at London Date, first Survey 26 July Last Survey 26 July 18 73
 on the Ship Her Majesty Master Curtis
 Tonnage 250 built at Calcutta When built 1836
 By whom built 110 H Owners S. R. Grant
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Both Green's Dry Dock and Afloat
 Last Survey, No. 16 Port Shanghai Classed 14 A1

REPAIRS, &c.

The Diagonal - doubling in the upper course of bottom on the "Port Row" dubbed bright to clear defective workmanship; one plank thro' piece, and the Yellow Metal sheathing patched.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Good</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>Good</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame at the openings <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Ditto Ditto at other places <u>Good</u>	Condition, how ascertained <u>See upon the deck</u>
Planksheers <u>Good</u>	Keelsons <u>Good</u>	Sails <u>Good and Sufficient</u>
Sheerstrakes <u>Good</u>	Clamps and Shelves <u>Good</u>	Anchors No. of <u>3 B. 15. 2 ft</u>
Topsides <u>Good</u>	Ceiling <u>Good</u>	Cables <u>Good</u>
Wales <u>Good</u>	Rudder <u>Good</u>	Hawsers and Warps <u>Good</u>
Plank (Bottom) and Counter <u>Good</u>	Copper <u>Good</u> When put on <u>1872</u>	Standing & Running Rigging <u>Sufficient</u>
Engine Room Skylights <u>Good</u>	Caulking of <u>3 Good</u>	Cargo and Main Hatchways <u>Good</u>
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Bottom, Deck, & Waterways <u>Good</u>	Hatches <u>Good</u>
General Observations and Opinion, <u>Is now in good, and efficient condition; and in my opinion eligible to remain as classed</u>	Scuppers <u>Good</u>	

The Amount of Entry Fee.....£ 1 : - : - is received by me,

Special.....2 - 2 - } 13/8/73

Certificate (if required) : : 5 : "

Committee's Minute 15th August 18 73

Character assigned Comp 13 A1



© 2021

Lloyd's Register Foundation