

REPORT of SURVEY for REPAIRS.

33328

No. in Reg. Book. 368 No. 32008 Survey held at London Date, first Survey Feb^r 14th Last Survey Feb^r 16th 1873
 on the Barque Wynaud Master A Findlay
 Tonnage 521 built at London When built 1854
 By whom built — Owners Redfern & Co
 Port belonging to London Destined Voyage Hobart Town
 If Surveyed Afloat or in Dry Dock Globe dry Dock (Smiths) & S.W. India docks
 Last Survey, No. 32008 Port London Classed Cons^d 13. A. 1.
 REPAIRS, &c.

Stripped off the Yellow metal sheathing
 Overhauled the Caulking of the Doubling planks
 and found the bulwark stansions. Rebuilt or recapped
 Rudder pinsles. Repitted Rudder and Steering gear.
 Resheathed with Yellow metal on felk.

Present Condition of the

Decks	good	Treenails	good	Windlass and Capstan	in good order
Waterways	11	Breasthooks and Stemson	11	Pumps	11
Comings	11	Transoms, Pointers, and Crutches	11	Boats	11
Upper Deck Beams & Fastenings	11	Timbers of the Frame at the openings	11	Masts, Yards, &c.	11
Lower Deck Beams & Fastenings	11	Ditto Ditto at other places	11	Condition, how ascertained	from the deck 11
Planksheers	11	Keelsons	11	Sails	11
Sheerstrakes	11	Clamps and Shelves	11	Anchors No. of	3 B. 1 S. 2 K 11
Topsides	11	Ceiling	11	Cables	11
Wales	11	Rudder	efficient	Hawsers and Warps	11
Plank (Bottom) and Counter	11	Copper	Fit & good When put on Now	Standing & Running Rigging	11
Engine Room Skylights	11	Caulking of	good	Cargo and Main Hatchways	good
Coal Bunker, Openings, Lids, &c.	11	Bottom, Deck, & Waterways	good	Hatches	good 11
Scuppers	good				

General Observations and Opinion,

She is in good condition and in my opinion is
 entitled to remain as Class'd Cons^d 13. A. 1.
 Samuel Presious

The Amount of Entry Fee.....£ : : is received by me,


Special..... 1 : 1 :

Certificate (if required) : 5 :

189 Committee's Minute 23rd Sept 1873

Character assigned Cons^d 13 A 1

Record (Ym 73)



© 2021

Lloyd's Register
 Foundation

LON658-0482

Myraut



© 2021

Lloyd's Register
Foundation