

33525

REPORT of SURVEY for REPAIRS.

Imperial & British

in No. *Survey held at* London *Date, first Survey* Dec 9th *Last Survey* Dec 11th 18 73
Book. on the S^t Prince Master Briggs
Tonnage 76 built at Jersey When built 1840
By whom built _____ Owners C. Murdoch
Port belonging to London Destined Voyage Coasting
If Surveyed Afloat or in Dry Dock Gun dock ways
Last Survey, No. 111 Port Amsterdam Classed 8
REPAIRS, &c. S.S. Jersey 71 — 5 A 1 in Red — 9.72

Recd. 17.12.73

I found this vessel on the ways and was informed that a damage survey was required; finding that the fore gripe and stem appeared badly damaged I recommended the vessel to be docked for examination; the owners declined to do this and have removed the vessel which is also due for annual survey —

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchor No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		
Hatches		

General Observations and Opinion,

Under the above circumstances I beg respectfully to leave this vessel's character in the hands of the Committee
Letter and remarks attached

The Amount of Entry Fee.....£ : : is received by me, Thos. W. Mason
Special..... : :
Certificate (if required) : :

Committee's Minute 19th December 1873
30th December 1873

Character assigned Deferred
write to owner
1/10/74 TBM

deferred
write owner
letter 20.12.73
Lloyd's Register
Foundation
9600-65907