

REPORT of SURVEY for REPAIRS.

Read 6.3.74

No. in **No.** Survey held at London Date, first Survey Last Survey 25th Feby 1874
eg. Book. on the B.K. Alice Master Hendall
Tonnage 337 built at Gloucester When built 1864-10-mo
By whom built Miller Owners Benyon
Port belonging to Newport Destined Voyage South America
If Surveyed Afloat or in Dry Dock West India Dock
Last Survey, No. 3260 Port Newport Classed 11 A.1
REPAIRS, &c. (H.J. Newpt-69) 10-70

Found the vessel loaded within twelve inches of metal line the yellow metal sheathing is said to have been renewed on felt in January 1873- at Port Louis-Mauritius. The receipts and certificates for which have been produced and are appended - dated & signed by -
D. Wales Feby 1-1873
Surveyor to Lloyd Agents
Port Louis
Mauritius

Present Condition of the

Decks <u>Good where seen</u>	Treenails <u> </u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u> </u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u> </u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the openings <u> </u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u> </u>	Ditto Ditto at other places <u> </u>	Condition, how ascertained <u>from deck</u>
Planksheers <u> </u>	Keelsons <u> </u>	Sails <u>Good & sufficient</u>
Sheerstrakes <u> </u>	Clamps and Shelves <u> </u>	Anchors No. of <u>3 B - 2 H - 1 1/2 m</u>
Topsides <u> </u>	Ceiling <u> </u>	Cables <u>Good</u>
Wales <u> </u>	Rudder <u>Good where seen</u>	Hawsers and Warps <u>and</u>
Plank (Bottom) and Counter <u> </u>	Copper <u>40 Yds</u> When put on <u>1873</u>	Standing & Running Rigging <u>sufficient</u>
Engine Room Skylights <u> </u>	Caulking of <u> </u>	Cargo and Main Hatchways <u>Good</u>
Coal Bunker, Openings, Lids, &c. <u> </u>	Bottom, Deck, & Waterways <u>Good where seen</u>	Hatches <u>Good</u>
Scuppers <u>Good</u>		

New main mast supplied to make good deficiencies the upper works and Vessels equipment in good condition

The Amount of Entry Fee.....£ : : is received by me, JW Blayell
Special.....
Certificate (if required) : :

Committee's Minute 18
Character assigned Record T 27m 731118

