

REPORT of SURVEY for REPAIRS.

33855
34012

No. in Reg. Book. **No.** Survey held at London Date, first Survey 15th Jan Last Survey 3rd Feb 1873
on the Comp. S. Douglas Castle Master R. Skinner
Tonnage 648 built at Glasgow When built 1864 - 10mo
By whom built Cornell Owners J. Skinner & Co.
Port belonging to Glasgow Destined Voyage Sidney
If Surveyed Afloat or in Dry Dock Ratcliff Dry Dock & London Dock

Recd. 12.2.73
Expd.

Last Survey, No. 3325 Port Glasgow Classed 16 A 1
REPAIRS, &c. None done (S.S. 69) (4. 71)

The yellow metal sheathing stripped off the bottom and elsewhere; the hold cleared; limbers and portable ceiling all fore and aft removed; Cement, frames, floors, and keel plate examined and found in good condition. The iron work from bilge to lower deck scraped clean and painted; the floors &c. exposed, scraped, and washed with cement (with the exception of those in after hold). The windlass unhooked and rood lining stripped. The chain cables ranged on deck, found good and sufficient. Iron hoops on the Rudder head repaired. Pulwarks on both sides, and houses on deck repaired. Caulked from keel to metal line and resheathed with yellow metal on floor. New hedge anchor 4 1/2 cwt. supplied.

Present Condition of the

Decks	Good	Boats	Where seen good	Windlass and Capstan	Good
Waterways	"	Greenails	"	Pumps	4 "
Comings	"	Breasthooks and Stemson	"	Boats	3 "
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Condition, how ascertained	from deck
Planksheers	"	Ditto Ditto at other places	"	Sails	2 suits "
Sheerstrakes	"	Keelsons	"	Anchors No. of	312. 14. 2K
les	"	Clamps and Shelves	"	Cables	Good
(Bottom) and Counter	"	Ceiling	"	Hawsers and Warps	and
Room Skylights	✓	Rudder	"	Standing & Running Rigging	sufficient
al Observations and Opinion,		Copper	Y. M. When put on non	Cargo and Main Hatchways	good
		Caulking of	Good where tested	Hatches	good
		Bottom, Deck, & Waterways			

The requirements of the "Second Special Survey" has been complied with. She is in a good and efficient condition, capable in my opinion to remain as classed, and to be noted the Register Book 44712. 73

Amount of Entry Fee.....£ is received by me,

Special..... 4: 4: 13/8/74

Certificate (if required).....

Committee's Minute 4th August 1874

Character assigned

S.S. 74 73
HT 74 73

James McNeill

1240-659207



© 2021

Lloyd's Register Foundation