

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. 1181 No. 1181 Survey held at London Date, first Survey 22 Aug 74 Last Survey 24 Aug 1874
 on the Ship Costa Rica Packet Master A. Pope Cory
 Tonnage 531 built at Guernsey When built 1861-7 mo
 By whom built Sebire Owners Le Lachter & Co
 Port belonging to Guernsey Destined Voyage Nelson by boat and St Katherine's
 If Surveyed Afloat or in Dry Dock Nelson by boat and St Katherine's

Last Survey, No. 23547 Port Liverpool Classed 15 Years assigned. 11.72 Character in Register Book. A.1

REPAIRS, OR EXAMINATION AS PER RULE

Remotalling &c. C.S.

Yellow metal sheathing removed and the bottom and keel sighted, recaulked from keel to metal line and the bottom sheathed with yellow metal over felt.

Cause of Repairs to be clearly stated.

Present Condition of the	
Decks <u>Good</u>	Treenails <u>Good</u>
Waterways <u>—</u>	Breasthooks and Stemson <u>—</u>
Comings <u>—</u>	Transoms, Pointers, and Crutches <u>—</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame at the openings <u>—</u>
Lower Deck Beams & Fastenings <u>—</u>	Ditto Ditto at other places <u>—</u>
Planksheers <u>—</u>	Keelsons <u>—</u>
Sheerstrakes <u>—</u>	Clamps and Shelves <u>—</u>
Topsides <u>—</u>	Ceiling <u>—</u>
Wales <u>—</u>	Rudder <u>—</u>
Plank (Bottom) and Counter <u>—</u>	Copper <u>Yellow</u> When put on <u>now</u>
Engine Room Skylights <u>—</u>	Caulking of <u>—</u>
Coal Bunker, Openings, Lids, &c. <u>—</u>	Bottom, Deck, & Waterways <u>Good</u>
Scuppers <u>Good</u>	Windlass and Capstan <u>Good</u>
Cargo and Main Hatchways <u>Good</u>	Pumps <u>—</u>
Hatches <u>Good</u>	Boats <u>—</u>
	Masts, Yards, &c. <u>—</u>
	Condition, how ascertained <u>Wh. from deck</u>
	Sails <u>Good</u>
	Anchors No. of <u>3/12 18th 24kg</u>
	Cables <u>Good</u>
	Hawsers and Warps <u>and</u>
	Standing & Running Rigging <u>sufficient</u>

General Observations, Opinion as to Class, &c. This vessel is now in good and efficient condition and in my opinion eligible to remain as classed; viz 15 A.1.

The Amount of Entry Fee ... £ : : received by me, Howe
 Special ... £ 1 : 1 : 5.7. 1875
 Certificate (if required) ... £ : 5 :
 (Travelling Expenses, if any, £)

Committee's Minute 6th July 1875

Character assigned 15 A.1

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation