

36.650
REPORT of SURVEY for REPAIRS, &c.

(Paid 15-10-77)
No. in Reg. Book. **No.** Survey held at London Date, first Survey Sept 13 Last Survey Oct 12 1877
1472 on the BK Cumberland Master _____
TONNAGE under Tonnage Deck 810 Built at Sunderland When built 1856
Ditto of Spar Deck, or Awning Deck _____ Owners A Adamson Port belonging to London
Ditto of Poop _____
Ditto of Raised Qr. Dk. _____
Ditto of Houses on Deck _____
Ditto of Forecastle _____
Gross Tonnage 881 Residence _____
Crew Space, as per Rule _____ By whom built _____
Register Tonnage, cut on Beam 861 Destined Voyage _____
Engine Room _____
Reg. Tons as St' mer, cut on Bm. _____
If Surveyed Afloat or in Dry Dock By J.R. Ballastin
Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck 50 ft. Years assigned. Character in Register Book.
Last Survey, No. 65 Port Mauritius Classed 13A1 4.77
Sent Mt 69-9 7/10
217' Len 75
REPAIRS, OR EXAMINATION AS PER RULE _____

At present owing to damage
the yellow Metal stripped off on both sides
from the bilge upwards and caulked under
the same & yellow Metal on felt to load line.

Present Condition of the				
Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Pumps
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the openings	<u>"</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	<u>"</u>	Ditto Ditto at other places	<u>"</u>	Condition, how ascertained
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Sails
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Anchors No. of <u>3 No. 44 No. 48</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	Cables
Wales	<u>"</u>	Rudder	<u>"</u>	Hawsers and Warps
Plank (Bottom) and Counter	<u>"</u>	Copper <u>3 Metal</u> When put on <u>1875</u>	<u>Good</u>	Standing & Running Rigging
Engine Room Skylights	<u>"</u>	<u>in felt</u> Caulking of <u>1877</u>		
Coal Bunker, Openings, Lids, &c.	<u>"</u>	Bottom, Deck, & Waterways	<u>Good</u>	
Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>	Hatches <u>Good</u>
General Observations, Opinion as to Class, &c.				

She is now in a good condition
and entitled to remain as classed

Senhouse Martineau

Damage fee £3.3-0

The Amount of Entry Fee£ : : : received by me, }
16/10/77 Special£ 1 : 1 : } 5 Nov 1877 }
Certificate (if required)£ - : 5 : }
(Travelling Expenses, if any, £)

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute 6th November, 1877.

Character assigned Cont of ...
DPW record Y.M. pt 77



© 2021
Lloyd's Register
Foundation

100662-0339

Cumberland



© 2021

Lloyd's Register
Foundation