

with nut and screw have been introduced viz. one bolt in each frame and in each strake of outside plating from the termination of the new fastenings in #73 upwards to the iron Sheer Trunk, the bolt in which is of 4. metal. The bolts in Waterway and Plank Roofs, with the precaution being ^{not now removed} ~~not now removed~~ a Waterway bolt has, however, been removed and found to be in excellent condition.

J. H. Longdon



© 2021

Lloyd's Register
Foundation