

REPORT of SURVEY for REPAIRS, &c.

No. 39048

No. in Survey held at *London*

Reg. Book.

Date, first Survey *15 March* Last Survey *17 March* 1880

(Received at London Office, *2.4.80*)

1041 on the *S. "Collingrove"*

Master *J. Sanderson*

TONNAGE under Tonnage Deck *745.93*

Ditto of Spar Deck, or Awning Deck

Ditto of Poop *107.97*

Ditto of Raised Qr. Dk. *11.65*

Ditto of Houses on Deck *31.59*

Ditto of Forecastle *897.14*

Gross Tonnage *35.76*

Crew Space, as per Rule *861.38*

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St' mer, cut on Bm.

Built at *Liverpool*

When built *1869*

Owners *A. L. Elder & Co*

Port belonging to *London*

Residence

By whom built *Living*

Destined Voyage *Adelaide*

If Surveyed Afloat or in Dry Dock

Bridge dry dock

(State Name of Dock)

Length of Poop

ft. Ditto, Forecastle

ft. Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Classed

16

At. 3.79

Last Survey, No. *37944*

Port *London*

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

S.P. 77.

26.77

Survey for improved class under amended Table I

Yellow Metal stripped off and bottom cleaned down. Caulked from keel to height of metal and retatched as before.

The present class of the ship is 16 yrs by 14 yrs Table I

It appears from the first entry report that the stem is very leaky and leaky, and all the planking from the keel upwards to the Waterways inclusive is of leaky 16 yrs.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Coal Bunker, Openings, Lids, &c.

Scuppers

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors

Cables

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

Roof

The Amount of Entry Fee ... £ ... received by me,

3/4/80 Special ... £ *6* : *6* : *7/4/80*

Certificate (if required)

to be sent as per margin... £ *5* : *4*

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

Wednesday April 6th 1880

Raised to 18 yrs

Wm. J. B. W.

Surveyor to Lloyd's Register of British and Foreign Shipping.

It is submitted that the vessel may be considered eligible under amended Table I to be raised to the 18 yrs class as recommended.



Lloyd's Register Foundation

Callaghan



© 2021

Lloyd's Register
Foundation