

REPORT of SURVEY for REPAIRS, &c.

39889

No. 39889
 No. in Survey held at London Date, first Survey 25 Nov Last Survey 29 Nov 1880
 Reg. Book. 301 on the S.S. "Benarty" Master Potter
 Tonnage under Tonnage Deck 1707 963 Built at Glasgow When built 1846-10
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop Owners Thompson & Co Port belonging to Leith
 Ditto of Raised Qr. Dk. Residence
 Ditto of Houses on Deck By whom built Barclay Destined Voyage Singapore via Cardiff
 Ditto of Forecastle Gross Tonnage 1724 If Surveyed Afloat or in Dry Dock West. I. dry dock
 Register Tonnage, cut on Beam
 Engine Room Reg. Tons as St' mer, cut on Bm. 1119
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.
 Last Survey, No. 25022 Port Iron Classed 100 A1.
 REPAIRS, OR EXAMINATION AS PER RULE 1179
 Cause of Repairs to be clearly stated.

The bottom cleaned, examined and recoated
 In consequence of ballast being in the hold, it is intended, on its removal at Cardiff, to prepare the vessel for the special survey and complete it at that port.

Present Condition of the	Goods	Treenails	Rivets	Keels	Windlass and Capstan
Decks	de	de	de	de	Pumps
Waterways	de	de	de	de	Boats
Comings	de	de	de	de	Masts, Yards, &c.
Upper Deck Beams & Fastenings	de	de	de	de	Condition, how ascertained
Lower Deck Beams & Fastenings	de	de	de	de	Sails
Planksheers	de	de	de	de	Anchors No. of
Sheerstrakes	de	de	de	de	Cables
Topsides	de	de	de	de	Hawsers and Warps
Wales	de	de	de	de	Standing & Running Rigging
Plank (Bottom) and Counter	de	de	de	de	Cargo and Main Hatchways
Engine Room Skylights	de	de	de	de	Hatches
Coal Bunker, Openings, Lids, &c.	de	de	de	de	
Scuppers	de	de	de	de	

General Observations, Opinion as to Class, &c.
 It is submitted that Mr. Lyell be apprised of the circumstances of this case

The Amount of Entry Fee ... £ : : received by me, }
 Special ... £1 : : }
 Certificate (if required) - }
 to be sent as per margin... }
 (Travelling Expenses, if any, £)

Committee's Minute Friday, December 17th 1880
 Character assigned Disapproved
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 LONDON



Form No. 2 for Repairs.—1,000—10/5/80.—
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.