

ANNUAL SURVEYS.

No. 40016 Survey held at London Date, first Survey 28 Dec^r/80 Last Survey 12th Jan^y 1881
 No. in on the Iron Bk "Mataura" Master A. Brown.
 Reg. Book. 788 Tonnage 253 Built at Glasgow When built 1868-12 mo
 By whom built Aitken. Owners New Zealand Ship^y C^o (Lim.)
 Port belonging to Lyttelton N.Z. Destined Voyage New Zealand.
 If Surveyed Afloat or in Dry Dock In the Canal Dry Dock.

Last Survey, No. 21589 Port of Iron Classed S.L. Lon. N^o 2-78. Years assigned. 7.78. Character in Register Book. *A.1.
 Present Condition of the
 Decks good Treenails rivets good
 Waterways D^o Breasthooks and Stemson D^o
 Comings D^o Transoms, ~~Pointers~~, and Crutches D^o
 Upper Deck Beams & Fastenings D^o Timbers of the Frame at the Openings D^o
 Lower Deck Beams & Fastenings D^o Ditto ditto at other places D^o
 Planksheers D^o Keelsons D^o
 Sheerstrakes D^o Clamps and Shelves D^o
 Topsides D^o Ceiling D^o
 Wales D^o Rudder D^o
 Plating (Bottom) and Counter D^o Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways good
 Windlass and Capstan good.
 Pumps D^o
 Boats D^o
 Masts, Yards, &c. D^o
 Condition, how ascertained from the deck.
 Sails good
 Anchors, No. of 3 B. 1 S. 2 K
 Cables complete
 Hawers and Warps sufficient
 Standing and Running Rigging good

General Observations, Opinion as to Class, &c. The bottom has been examined, cleaned & coated and the rudder pintles rebushed.
All the hatches in the flat of ceiling lifted except in way of the ballast amidships; the cement examined & found in good condition and adhering well to the iron.
Committee has sanctioned S.L. N^o 3 being deferred till return from voyage - see Secretary's letter dated 29th Dec^r/80.
This vessel appears to be eligible to remain as classed.

Committee's Minute Friday, January 24th. 18 81.
 Character assigned The S.L. N^o 3
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. 40016 Survey held at London Date, first Survey 28 Dec^r/80 Last Survey 12th Jan^y 1881
 No. in on the Iron Bk "Mataura" Master A. Brown.
 Reg. Book. 788 Tonnage 253 Built at Glasgow When built 1868-12 mo
 By whom built Aitken. Owners New Zealand Ship^y C^o (Lim.)
 Port belonging to Lyttelton N.Z. Destined Voyage New Zealand.
 If Surveyed Afloat or in Dry Dock In the Canal Dry Dock.

Last Survey, No. 21589 Port of Iron Classed S.L. Lon. N^o 2-78. Years assigned. 7.78. Character in Register Book. *A.1.
 Present Condition of the
 Decks good Treenails rivets good
 Waterways D^o Breasthooks and Stemson D^o
 Comings D^o Transoms, Pointers, and Crutches D^o
 Upper Deck Beams & Fastenings D^o Timbers of the Frame at the Openings D^o
 Lower Deck Beams & Fastenings D^o Ditto ditto at other places D^o
 Planksheers D^o Keelsons D^o
 Sheerstrakes D^o Clamps and Shelves D^o
 Topsides D^o Ceiling D^o
 Wales D^o Rudder D^o
 Plank (Bottom) and Counter D^o Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways good
 Windlass and Capstan good.
 Pumps D^o
 Boats D^o
 Masts, Yards, &c. D^o
 Condition, how ascertained from the deck.
 Sails good
 Anchors, No. of 3 B. 1 S. 2 K
 Cables complete
 Hawers and Warps sufficient
 Standing and Running Rigging good

General Observations, Opinion as to Class, &c. The bottom has been examined, cleaned & coated and the rudder pintles rebushed.
All the hatches in the flat of ceiling lifted except in way of the ballast amidships; the cement examined & found in good condition and adhering well to the iron.
Committee has sanctioned S.L. N^o 3 being deferred till return from voyage - see Secretary's letter dated 29th Dec^r/80.
This vessel appears to be eligible to remain as classed.

Committee's Minute Friday, January 24th. 18 81.
 Character assigned The S.L. N^o 3
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18