

Report of Survey for Repairs of Engines and Boilers.

(Received at London Office, 3.11.81)

22/11/81 Vo. 40547
 No. in Survey held at London Date, first Survey Oct 28th Last Survey Oct. 28th 1881
 eg. Book. on the Machinery of the S. S. "Leviot" (Number of Visits 1)
 Tonnage, Gross 2057 Built at Sunderland When built 1871
 Ditto, Net 1349 Owners E. M. Howard & Co. Port belonging to London
 Diameter of Cylinder 37 + 70 Engines made by Thompson, Boyd & Co. When made 1871
 Length of Stroke 36 Boilers made by When made 1880
 Pressure of Steam 75 lbs. If Surveyed Afloat or in Dry Dock S. S. M. Dry Dock Classified 100A1
 Registered Horse Power 250 (State name of Dock.)
 Last Survey No. 40329 Port Lon. Lloyds M.C. 12.50.

Particulars of Repairs and Examination In Annual Survey.

(State cause of Repairs.)

Vessel placed in dry dock sea connections examined & found to be in good condition. A new propeller has been fitted to a tail shaft that has already been used, fitted with new brass liners. The High pressure cylinder has been bored out & a new piston fitted.

General Observations, Opinion, and Recommendation:— *As far as seen this vessel appears eligible to remain as classed.*

Entry or Registering Fee... £ : :
 (per Section 27.)
 Survey Fee (per Section 28) ... £ : : received by me,
 Certificate (if required) ... £ : : 188
 to be sent as per margin.
 (Travelling Expenses, if any, £)

Committee's Minute

Friday, November, 25th 1884

Assigned

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



LON 666-0105

It is submitted that this vessel
is eligible to remain as
Classed

Am 3/11/8



© 2021

Lloyd's Register
Foundation