

#40576

# Report of Survey for Repairs of Engines and Boilers.

No. \_\_\_\_\_

No. in Reg. Book. \_\_\_\_\_

Survey held at London

Date, first Survey Nov: 18<sup>th</sup> and Last Survey Nov: 29<sup>th</sup> 1881

5 on the Machinery of the S.S. "De Bay"

(Number of Visits 2)

Year \_\_\_\_\_

Tonnage, Gross 1664

Built at Newcastle

When built 1881

Ditto, Net 1083

Owners Capper Alexander & Co.

Port belonging to Cardiff

Diameter of Cylinder 30" + 53"

Engines made by Palmer's Co.

When made 1881

Length of Stroke 42"

Boilers made by Ditto

When made 1881

Pressure of Steam 80 lbs.

If Surveyed Afloat or in Dry Dock Pontoon

Classed 100A1

Registered Horse Power 160

Last Survey No. \_\_\_\_\_

Port \_\_\_\_\_

Years assigned, \_\_\_\_\_

Character in Register Book, \_\_\_\_\_

## Particulars of Repairs and Examination For Annual Survey

*Vessel placed on Pontoon, sea connections examined & found to be in good condition. Propellers found to be sound, & the tail shaft a good working fit in Stem Bush. Wheel Gearing & Plummer Blocks for driving propellers examined & found to be sound, the pedestals showing no signs of having been shaken.*

General Observations, Opinion, and Recommendation:— *As far as seen this vessel appears eligible to remain as classed.*

Entry or Registering Fee... £ : : \_\_\_\_\_

Survey Fee (per Section 28) ... £ — : — : \_\_\_\_\_

Certificate (if required) ... £ : : \_\_\_\_\_

received by me, \_\_\_\_\_

188 \_\_\_\_\_

(Travelling Expenses, if any, £ \_\_\_\_\_)

Committee's Minute Tuesday, December 6th, 1881.

Assigned \_\_\_\_\_

Geo. E. Merriamson  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



LON 666-0193



It is submitted that this vessel  
is eligible to be entered as  
Classed

M 4/2/87



© 2021  
Lloyd's Register  
Foundation