

Report of Survey for Repairs of Engines and Boilers.

740578

No. _____ (Received at London Office, 21. 11. 81)

No. in Reg. Book. Survey held at London Date, first Survey and Last Survey 11 Nov 1881

on the Machinery of the S. S. Jaymouth Castle (Number of Visits 1)

Tonnage, Gross 1824 Built at Glasgow When built 1877

Ditto, Net 1472 Owners S. Currie & Co Port belonging to London

Diameter of Cylinder 36 63 Engines made by Barclay Curle & Co When made 1877

Length of Stroke 89 Boilers made by u u When made 1877

Pressure of Steam 60 If Surveyed Afloat or in Dry Dock (State name of Dock.) _____

Registered Horse Power 190 Classed 100 A 1

Last Survey No. _____ Port _____ Lloyds M.C. 581

Particulars of Repairs and Examination Annual

(State cause of Repairs.)

Examined Seacocks & connections & found them in good condition

General Observations, Opinion, and Recommendation:— As far as seen the machinery of this vessel appears eligible to remain as classed

Entry or Registering Fee... £ : :
 Survey Fee (per Section 28) ... £ : : received by me,
 Certificate (if required) ... £ : : 188 }
 to be sent as per margin.

C. R. Brown
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Tuesday, December, 6th, 1881.

Assigned _____



LONG66-0199

Insert Character precisely as in the Register Book.

Submitted that this vessel
remain in charter.

M
19.11.81



© 2021
Lloyd's Register
Foundation