

Report of Survey for Repairs of Engines and Boilers.

No. 792  
Survey held at London  
Date, first Survey 24<sup>th</sup> March Last Survey 14<sup>th</sup> April 1882  
on the Machinery of the Screw Steamer Erasmus Wilson (Number of Visits 5)  
Tonnage, Gross 805 Built at Hartlepool When built 1876  
Ditto, Net 497 Owners S. Clarke & Co. Port belonging to London  
Diameter of Cylinder 27" 850 1/2 Engines made by Blair & Co (Lim<sup>d</sup>) When made 1876  
Length of Stroke 33 Boilers made by Do. When made 1876  
Pressure of Steam 70 lbs If Surveyed Afloat or in Dry Dock Limehouse Dock (State name of Dock.)  
Registered Horse Power 99 Classed 90 A 1  
Last Survey No. 40529 Port Querc Lloyd's M.B. 4.82

Particulars of Repairs and Examination Annual  
(State cause of Repairs.)  
High and Low pressure pistons, all pumps and sea connections overhauled & put in good working order  
Lower portions of Combustion chambers renewed in main boiler & supported with new screwed stays  
Propeller drawn back & refitted

General Observations, Opinion, and Recommendation:— The machinery of this vessel is now in good working order and eligible in my opinion to have the notification Lloyd's M.B. 4.82 recorded

Entry or Registering Fee... £ 7 : 0 : 0  
Survey Fee (per Section 28) ... £ 2 : 2 : 0 received by me, David Purves  
Certificate (if required) ... £ - : 2 : 6  
(Travelling Expenses, if any, £ )  
Committee's Minute Friday, April 28th, 1882  
Assigned Lloyd's M.B. 4.82  
London.  
Lloyd's Register Foundation  
LON663-0041



It is submitted that this  
vessel is eligible to have  
the notification No. MC  
4.82 recorded, the vessel  
being subject to  
annual survey

M 25/4/82



© 2021  
Lloyd's Register  
Foundation

Boiler of Survey for Repairs of Engines and Boilers.