

Report of Survey for Repairs of Engines and Boilers.

No. 1214 on the Machinery of the S. S. Luppicich (Received at London Office, 14.7.82)

No. in Reg. Book. 1214 Survey held at London Date, first Survey 6 June Last Survey 15 June 1888

Tonnage, Gross 1401 Built at Newcastle When built 1878

Ditto, Net 893 Owners Angier Bros Port belonging to London

Diameter of Cylinder 30 56 Engines made by Black Hawthorn When made 1878

Length of Stroke 39 Boilers made by Black Hawthorn When made 1878

Pressure of Steam 75 If Surveyed Afloat or in Dry Dock S. W. 78k. Years assigned 100 A1

Registered Horse Power 135 (State name of Dock.) Classed 100 A1

Last Survey No. 7.81 Port Liverpool

Particulars of Repairs and Examination Part Special Survey.

(State cause of Repairs.)

This vessel was not docked & the sea connections have not been seen.

Examined Boilers & found them in good condition.

Examined Safety valves, slide valves, cylinder pumps and crankshaft and found them in a good condition.

General Observations, Opinion, and Recommendation:— As far as seen the machinery appears to be in a safe working condition and is in my opinion eligible to have the notification L. M. C. renewed as soon as the sea cocks & connections have been seen, and to have the notification B. S. 6. 82 recorded

Entry or Registering Fee... £ " : " : "

Survey Fee (per Section 28) ... £ 3 : 3 : 0 received by me, J. F. E.

Certificate (if required) ... £ : 2 : 6 } 20/7 1882

(Travelling Expenses, if any, £ )

Committee's Minute Tuesday, 18th July, 1882.

Assigned B. S. 6, 82

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Lloyd's Register Foundation



Has submitted that this vessel is  
eligible to have the notification  
BS 6.82 recorded

11/1/52

Address - 100 St. Andrews



© 2021

Lloyd's Register  
Foundation

Office of the Registrar, Register of Engineers and Engineers