

# Report of Survey for Repairs of Engines and Boilers.

No. \_\_\_\_\_ (Received at London Office, 21 Jan 83.)  
No. in Reg. Book. Survey held at London Date, first Survey 11th Nov. Last Survey 2 January 1883  
354 on the Machinery of the S. S. Libra (Number of Visits 4)  
Tonnage, Gross 1034 Built at Dundee When built 1869  
Ditto, Net 570 Owners General Steam Nav Co Port belonging to London  
Diameter of Cylinder 43 78 Engines made by N E Marine Eng Co When made 1876  
Length of Stroke 36 Boilers made by \_\_\_\_\_ When made 1876  
Pressure of Steam 65 If Surveyed Afloat or in Dry Dock General Steam Nav Co Classed +A1  
Registered Horse Power 250 (State name of Dock.) Dry Dock Character in Register Book. 2.82  
Last Survey No. \_\_\_\_\_ Port \_\_\_\_\_ + LMC. 280

Particulars of Repairs and Examination Special Boiler Survey No 3  
(State cause of Repairs.)  
Examined Boilers and found them in a good condition  
The cylinders, slide valves and crank were opened and found to be in a good condition  
The sea cocks & connections were found to be in a good condition  
The safety valves were in good working condition

General Observations, Opinion, and Recommendation:— The machinery of this vessel appears to be in a safe working condition and is in my opinion eligible to have the notification + LMC 1.83 recorded in the Register Book.

Entry or Registering Fee... £ 1 : 10 : -  
Survey Fee (per Section 28) ... £ 3 : 3 : -  
Certificate (if required) ... £ : 5 : -  
(Travelling Expenses, if any, £ )  
Committee's Minute Tuesday 16th January 1883  
Assigned + M. L. B. subject to  
received by me, Ad. Browner 1883  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Insert Character precisely as in the Register Book.

LON 669-0454



It is submitted that this vessel is  
eligible to have the notification + L.M.B 1.83  
subject to the main boilers being  
renewed in 12 months on account of  
their age

D.S.  
6/1/83



© 2021

Lloyd's Register  
Foundation