

No. 845. Survey held at Antwerp Date, first Survey 22 May Last Survey 23 May 1883.

No. in 10 Book. on the Steam S.S. "William Burkitt" Master J. W. Freeman
Net 1232 Built at Newcastle When built 1878 11th 4236
Tonnage Gross 1902 By whom built T. Leslie & Co Owners Lane, Suters & Co
Under Dk. 1771 Port belonging to London Destined Voyage Antwerp - Spain
If Surveyed Afloat or in Dry Dock in City Dry Dock No 5
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed 100 3.82
Years assigned. Character in Register Book.

Present Condition of the
Decks good
Waterways "
Comings "
Upper Deck Beams & Fastenings "
Lower Deck Beams & Fastenings "
Plans "
Sheerstrakes "
Topsides "
Wales "
Planks (Bottom) and Counter "

Ironwork good
Breasthooks and Stems "
Transoms, Pointers, and Crutches "
Timbers of the Frame at the Openings "
Ditto ditto at other places "
Keelsons "
Clamps and Shelves "
Ceiling "
Rudder "
Copper or Y.M. transoms When put on new
Caulking of "
Bottom, Deck, & Waterways good

Windlass and Capstan good
Pumps "
Boats "
Masts, Yards, &c. "
Condition, how ascertained "
Sails "
Anchors, No. of 6
Cables stated to be complete
Hawsers and Warps good
Standing and Running Rigging "

Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
General Observations, Opinion as to Class, &c. Placed in Dry Dock and surveyed and accounted of having struck the bottom heavily when leaving the Spire for the Mediterranean.
Examined the ship all outside & inside including equipment as far as practicable
and found all appear to be in good condition, the ship fit to serve dry & perishable
goods to and from all parts of the world and worthy to be continued as classed.
Machinery survey not wanted.

Committee's Minute TUESDAY 29 MAY 1883 18

Character assigned 100
wrote to have
29/5/83

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) 5/ Paid 24/5 1883.
See remark 2.2. 27 May 1883
LONB70-0101

(The Surveyors are requested not to write on the back of the Certificate.)

(Insert Character precisely as in Register Book.)