

# Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office,

THURS 7 MAY 1885

To. *London* Date, first Survey *30 March* Last Survey *1 April 1885*  
No. in Reg. Book. *76* Survey held at *London* on the Machinery of the *S.S. Johnes Lanthorn* (Number of Visits *2*)  
Tonnage, Gross *801* Built at *N. Shields* When built *1865-6*  
Ditto, Net *573* Owners *Harris & Dixon* Port belonging to *London*  
Diameter of Cylinder *38 38* Engines made by *R & W Hawthorn* When made *1865*  
Length of Stroke *30* Boilers made by *When made 1865*  
Pressure of Steam *35* If Surveyed Afloat or in Dry Dock *Lincklin Dock* Character in Register Book. *90 A-5.84*  
Registered Horse Power *90*  
Last Survey No. *BS. 7.84* Port *LM 29.82*

Particulars of Repairs and Examination *Boiler Survey*  
(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from repairs due to other causes. State also the dates and initials of any letters respecting this case.)  
*Examined sea-cocks & connections & found them good. A new propeller has been fitted.*  
*Examined main boiler & found it in a good condition. Patch has been fitted in starboard furnace.*  
*The safety valves were found to be in a good working order for 35 lb pressure.*


General Observations, Opinion, and Recommendation:— *As far as seen the*  
(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)  
*machinery of this vessel appears to be in a safe working condition and eligible in my opinion to have the notification B.S. 4.85. recorded in the Register Book.*

Fee or Registration Fee (per Sec. 27)	£	:	:
Survey Fee (per Section 28)	£	1	1
Special Damage Fee (per Section 28)	£	:	:
Certificate (if required)	£	:	:
Travelling Expenses (if chargeable)	£	:	:

received by me, *[Signature]*  
1885

*C. J. Brown*  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute *TUESDAY 16 JUNE 1885*  
Assigned *B.S. 4.85*





It is submitted that this vessel is  
eligible to have the notification  
B. S. 4.85 recorded the boilers being  
subject to resurvey as per Rule.

W.F.  
7/5/85.



© 2021

Lloyd's Register  
Foundation