

45348

# Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office, TUESDAY 15 SEPT 1885)

No. 425 on the Machinery of the S. S. Drummond Castle Number of Visits 5  
 No. in Reg. Book. 425 Survey held at London Date, first Survey 18 Aug Last Survey 29 Aug 1885  
 Tonnage, Gross 3705 Built at Glasgow When built 1881 2  
 Ditto, Net 2381 Owners D. Currie & Co Port belonging to London  
 Diameter of Cylinder 57.88 Engines made by J. Elder & Co When made 1881  
 Length of Stroke 57 Boilers made by (J) When made 1881  
 Pressure of Steam 75 If Surveyed Afloat or in Dry Dock Thames T.Ws. Character in Register Book. 100 A1  
 Registered Horse Power 6.85 Classed 100 A1  
 Last Survey No.          Port          + L.M.C. 4.81

Particulars of Repairs and Examination Special Survey No 1  
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined sea cocks & connections & found them good. Four new blades have been fitted to the propeller box.  
Examined the two main (double ended) boilers & one superheater & the donkey boilers & found them good.  
Examined main & donkey boiler safety valves & found them good.  
Examined slides and high & low pressure cylinders & pumps & found them in a good condition  
Examined crankshaft & found it in a good condition.  
The safety valves have been set to blow at 75 lbs.

General Observations, Opinion, and Recommendation:— The machinery of this vessel appears to be in a safe working condition and is in my opinion eligible to have the notification + L.M.C. 8.85 recorded in the Register Book  
 (State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

Office or Registration Fee (per Sec. 27) £ : :  
 Survey Fee (per Section 28) £ 4:4-  
 Special Damage Fee (per Section 28) £ : :  
 \*Certificate (if required) £ : :  
 Travelling Expenses (if chargeable) £ : :


received by me, [Signature]  
12.12.1885

[Signature]  
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

FRIDAY 13 SEPT 1885

Committee's Minute  
 Assigned [Signature]

+ L.M.C. 8.85 4/12/85



Lloyd's Register Foundation

LONG675-0475

State if a Report is also sent on the Hull of the Ship

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that this vessel  
is eligible to have the notification  
Smb 8 55 recorded.

D.S.

14/9/85.



© 2021

Lloyd's Register  
Foundation