

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office, _____)

No. _____
 No. in Reg. Book. 178 Survey held at London Date, first Survey 18th Sept Last Survey 30 Oct 1885
 on the Machinery of the S. S. "Aegean" (Number of Visits 7)
 Tonnage, Gross 1157 Built at Glasgow When built 1870 5th Year Month
 Ditto, Net 750 Owners F. F. Reid Port belonging to Leith
 Diameter of Cylinder 31 54 Engines made by London & Glasgow Co When made 1870
 Length of Stroke 33 Boilers made by (C) When made 1882
 Pressure of Steam 65 If Surveyed Afloat or in Dry Dock (State name of Dock.) _____
 Registered Horse Power 150 Classed * A1
 Last Survey No. _____ Port _____ + N.B. 82. L.M.C. 5.82

Particulars of Repairs and Examination Special Survey

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined sea-cocks & connections & found them good. The stern tube has been relined. The tailshaft was found to be sound.
 Examined 2 main and one donkey boiler and found them in a good condition.
 Examined the safety valves, slide valves, high and low pressure cylinders and pumps & found them in a good condition.
 Examined crankshaft and found it in a good condition.
 The vessel has left without having the safety valves tested.


General Observations, Opinion, and Recommendation:— As far as seen the machinery of this vessel is in a safe working condition and eligible in my opinion to have the notification L. M. C. 1185 recorded provided the safety valves are found to blow off at 65 lbs pressure.

Office or Registration Fee (per Sec. 27) £ : :
 Survey Fee (per Section 28) £ 33 -
 Special Damage Fee (per Section 28) £ : :
 *Certificate (if required) £ : :
 Travelling Expenses (if chargeable) £ : :

received by me } A. S.
12-11 1885

C. S. Bromley
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute _____
 Assigned _____
TUESDAY 10 NOV 1885
L.M.C. 10, 85



Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that this vessel
is eligible to have the notification
Lomb 10.85 recorded
subject to the testy of
safety valves.

W.P.

10/11/85



© 2021

Lloyd's Register
Foundation