

Report of Survey for Repairs, &c., of Engines & Boilers.

No.

No. in
Reg. Book.

Survey held at

London

Date, first Survey

19 Aug

Last Survey

30 Nov 1885

437

on the Machinery of the

S. S. "Lishon"

(Number of Visits 3)

Tonnage, Gross

1334

Built at

W. Harlepool

When built

1871

Year

Ditto, Net

860

Owners

J. Hall jun & Co

Port belonging to

London

Diameter of Cylinder

27 57

Engines made by

Blair & Co

When made

1871

Length of Stroke

36

Boilers made by (i)

When made

1871

Pressure of Steam

70

If Surveyed Afloat or in Dry Dock

London DK

Classed

100 A1

Registered Horse Power

120

Last Survey No.

Port

M.S. 1182. BS 6.84

Particulars of Repairs and Examination

New Tubes in Boilers &

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

annual boiler survey.

Examined the two main boilers and found them in a good condition. A few patches have been fitted on the furnaces and combustion chambers & outside seams.

All boiler tubes except stay tubes have been renewed.

Examined donkey boiler & found it good. The shell plate near furnace door has been renewed.

The safety valves were found to be in good order and to blow off at 70 lbs.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

As far as seen the machinery of this vessel is in a safe working condition and eligible in my opinion to have the notification B.S. 9. 85 recorded in the Register Book

Office or Registration Fee (per Sec. 27) £ :

Survey Fee (per Section 28) £ 2 : 2

Special Damage Fee (per Section 28) £ :

*Certificate (if required) £ : 2 : 6

Travelling Expenses (if chargeable) £ :

received by me,

23/12/1885

Y.B.M.

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

TUESDAY 8 DEC 1885

Assigned

B.S. 11.00



Lloyd's Register Foundation

LON 676 - 0172

It is submitted that this vessel
is eligible to have the notification
B.S. 11-85 recorded the boilers
being subject to resurvey as
per Rule.

D.F.

4/12/85.



© 2021

Lloyd's Register
Foundation