

Report of Survey for Repairs, &c., of Engines & Boilers.

425666

No. _____ (Received at London Office, _____)

No. in Reg. Book. Survey held at London Date, first Survey 4 Dec Last Survey — 188 5

8 on the Machinery of the S. S. "Baghdadi" (Number of Visits 1)

Tonnage, Gross 1704 Built at Newcastle When built 1885 6

Ditto, Net 1104 Owners Persian Gulf S.S. Co Port belonging to London

Diameter of Cylinder 21 3/4 Engines made by W. Richardson & Co When made 1885

Length of Stroke 39 Boilers made by (S) When made 1885

Pressure of Steam 150 If Surveyed Afloat or in Dry Dock Bridge Dock (State name of Dock.)

Registered Horse Power 200 Classified 100 A1 8 85

Last Survey No. _____ Port _____ + L.M.C. 8 85

Particulars of Repairs and Examination Seacocks

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined Seacocks & connections & found
Newport.

It is submitted that this vessel is eligible to remain as classed M 14/12/85

General Observations, Opinion, and Recommendation:— As far as seen

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

The machinery of this vessel appears to be in a safe working condition and is in my opinion eligible to remain as classed

Office or Registration Fee (per Sec. 27) £ : :
 Survey Fee (per Section 28) £ : :
 Special Damage Fee (per Section 28) £ : :
 *Certificate (if required) £ : :
 Travelling Expenses (if chargeable) £ : :
 received by me, 1885

C. W. Shrimpton
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute _____
 Assigned _____
 FRIDAY 18 DEC 1885