

45925

FRIDAY 28

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office,

No. 36 in Survey held at London Date, first Survey 19th Dec 1886
Reg. Book. on the Machinery of the SS Rainbow (Number of Visits 1)
Tonnage, Gross 1086 Built at Dundee When built 1871
Ditto, Net 591 Owners General Steam N. Co. Port belonging to London
Diameter of Cylinder 42 + 70 Engines made by Howland Bros. When made 1871
Length of Stroke 36 Boilers made by Do When made 1885
Pressure of Steam 65 lbs. If Surveyed Afloat or in Dry Dock Dry Dock Classed 100 A 1
Registered Horse Power 250 (State Name of Dock.) 2.85
Last Survey No. 2.85 Port London

Particulars of Repairs and Examination on account of docking

(State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined Sea connections found them satisfactory
New propeller fitted.

General Observations, Opinion, and Recommendation :--

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

The machinery of this vessel is now in good order and safe
working condition and eligible in my opinion to remain as
classed.

Submitted that this vessel is eligible to remain as classed
MM
25-2-86

Office or Registration Fee (per Sec. 27)	£	:	:
Survey Fee (per Section 28)	£	:	:
Special Damage Fee (per Section 28)	£	:	:
*Certificate (if required)	£	:	:
Travelling Expenses (if chargeable)	£	:	:

received by me, 188

David Jones
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute TUESDAY 9 MARCH 1886 FRIDAY 12 MARCH 1886 TUESDAY 15 MARCH 1887
Assigned