

46121

Report of Survey for Repairs, &c., of Engines & Boilers.

No.

(Received at London Office,)

No. in
Reg. Book.

Survey held at

London

Date, first Survey

15 April

Last Survey

1886

649 on the Machinery of the

S. S. "Eury"

(Number of Visits

Year Month

Tonnage, Gross

1353

Built at

Hull

When built

1872 1

Ditto, Net

881

Owners

W S Bailey

Port belonging to

Hull

Diameter of Cylinder

31 7/8 58

Engines made by

Gilbert & Cooper

When made

1872

Length of Stroke

36

Boilers made by (i)

When made

1881

Pressure of Steam

72

Registered Horse Power

130

If Surveyed Afloat or in Dry Dock

(State name of Dock.)

Millwall Dock

Classed

90 A1

8.84

Last Survey No.

Port

A L M C. 884 BS 3.85.

Particulars of Repairs and Examination

Annual

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined Seacocks & connections & found them good.

It is submitted that this vessel is eligible to remain as classed M 24/4/86

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

As far as seen the machinery of this vessel is in a safe working condition & eligible in my opinion to remain as classed.

Office or Registration Fee (per Sec. 27)

£

:

:

Survey Fee (per Section 28)

£

:

:

Special Damage Fee (per Section 28)

£

:

:

*Certificate (if required)

£

:

:

Travelling Expenses (if chargeable)

£

:

:

received by me,
188

Committee's Minute

FRIDAY 7 MAY 1886

Assigned

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

