

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office,

No. *61* Port of *London*
 No. in Reg. Book. *61* Survey held at *London* Date, first Survey *22 July* Last Survey *1886*
 on the Machinery of the *S. S. Nautilus* (Number of Visits *1*)
 Tonnage, Gross *718* Built at *Sunderland* When built *1874 11*
 Ditto, Net *467* Owners *General Steam Navigation Co* belonging to *London*
 Diameter of Cylinder *26 47* Engines made by *G. Clark* When made *1874*
 Length of Stroke *33* Boilers made by *(i)* When made *1885*
 Pressure of Steam *65* If Surveyed Afloat or in Dry Dock *General Steam Nav Co* Classified *90 A1*
 Registered Horse Power *95* (State name of Dock.) *Co Dock* *10 85*
 Last Survey No. *135-12-85* Port *London* *Lme. 284*

Particulars of Repairs and Examination *Seacconnections*
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)
Examined Seacocks & connections & found them good.

General Observations, Opinion, and Recommendation:— *As far as seen the*
 (State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)
machinery of this vessel is in a safe working condition and is in my opinion eligible to remain as classed.

Office or Registration Fee (per Sec. 27)	£	:	:	} received by me, } 188
Survey Fee (per Section 28)	£	:	:	
Special Damage Fee (per Section 28)	£	:	:	
*Certificate (if required)	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	

C. J. Stoney
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute *FRIDAY 13 AUGUST 1886*

Assigned



© 2021
 Lloyd's Register
 Foundation

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character of Ship and Machinery precisely as in the Register Book.

LON 678-0126