

Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office,

No. *875* Port of *London* Date, first Survey *27 July* Last Survey *1886*
 Reg. Book. Survey held at *London* (Number of Visits *1*)
 on the Machinery of the *S. S. Miranda* Year Month
 Tonnage, Gross *996* Built at *Newcastle* When built *1865 3*
 Ditto, Net *736* Owners *J. Fenwick & Son* Port belonging to *London*
 Diameter of Cylinder *25 48* Engines made by *Palmer* When made *1871*
 Length of Stroke *30* Boilers made by *(c)* When made *1871*
 Pressure of Steam *75* If Surveyed Afloat or in Dry Dock *London Docks* Classed *80 A1*
 Registered Horse Power *140* (State name of Dock.) Character in Register Book. *3. 86.*

Last Survey No. *MS. 9. 84* BS. *5 84*
 Particulars of Repairs and Examination *Annual Boiler Survey*
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined the two main boilers and the Superheater & found them in a good condition. The safety valves (weights & levers) were found to be in an efficient working condition for the working pressure (75 lb).

General Observations, Opinion, and Recommendation:— *As far as seen the machinery of this vessel is in a safe working condition and eligible in my opinion to have the notification B.S. 7. 86 recorded in the Register Book*
 (State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

Office or Registration Fee (per Sec 27) £ : :
 Survey Fee (per Section 28) £ 1 : :
 Special Damage Fee (per Section 28) .. £ : :
 *Certificate (if required) £ : :
 Travelling Expenses (if chargeable) £ : :

received by me, *H.S.*
30.8.1886


H.S.
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

FRIDAY 27 AUGUST 1886

Committee's Minute

Assigned

B.S. 7. 86



© 2021
 Lloyd's Register
 Foundation

Form No. 9 - 1886 - 2000, 91, 5/86. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.

5810-8E9N07