

47287

Report of Survey for Repairs, &c., of Engines & Boilers.

No. 47287 Port of _____ (Received at London Office, _____)
No. in Reg. Book. Survey held at London Date of Writing Report _____ 188

3 on the Machinery of the S. S. "Aberdeen" (No. of Visits _____)
Tons, Net 971 Gross 1579
X Surveyed Afloat or in Dry Dock Commercial Vessel built at Aberdeen in 1883 Engines made in 1883
(State name of Dock.)

No. of Main Boilers 2 Made in 1883 Donkey Boiler made in 18 _____ Working Pressure, Main Boilers 100 lbs.;
Working Pressure, Donkey Boiler 70 lbs.; Owners Adam & Co. Port Aberdeen
Last Survey No. 47099 Port Lon. Class of Vessel and Machinery 100 A1 L.M.C.3.83
(As in Register Book).

Particulars of Repairs and Examination Completion of S. S. No. 1.
(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.)

Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Boiler separately (including the Donkey Boiler, if any),
and make a thorough examination at this time?.....

If this was not done, state for what reasons?.....
And what parts of the Boilers could not be thus thoroughly examined?.....

Also what special means, in the absence of internal examination, were adopted by the
Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?.....

Main boiler safety valves set under steam to 100 lbs.

General Observations, Opinion, and Recommendation:— The Safety valves now being
(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey.)
set to the working pressure it is submitted that the vessel is eligible
to remain as classed.

Office or Registration Fee (per Sec. 27).....	£ : :	Fees applied for
Survey Fee (per Section 28).....	£ : :	188
Special Damage, Fee (per Section 28).....	£ : :	Received by me,
*Certificate (if required) as per margin.....	£ : :	
Travelling Expenses (if chargeable).....	£ : :	

Geo. B. Mearns
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute FRIDAY 10 JUNE 1887
Assigned J. M. C. 3, 87

T. & S. Form No. 8. The Surveyors are required to sign the Report in the presence of the Committee, and to sign the Register Book.

Insert Character of Ship and Machinery precisely as in the Register Book.

LON 680-0120



It is submitted that this vessel
is eligible to have the
notification LMB 3.87
recorded.

29

25/5/87

Vertical text bleed-through from the reverse side of the page, appearing as faint, mirrored characters.

Vertical text bleed-through from the reverse side of the page, appearing as faint, mirrored characters.



© 2021
Lloyd's Register
Foundation

Vertical text bleed-through from the reverse side of the page, appearing as faint, mirrored characters.