

REPORT of SURVEY for REPAIRS, &c.

No. 415 Date of Writing Report 9th May 1890 Port of London
No. in Reg. Book. Survey held at London Date, First Survey 30th April Last Survey 7th May 1890
(No. of Visits 4) Master F. W. Gray

415 on the Iron Screw Steamer TOPAZE
TONNAGE:— Built at Newcastle By whom C. S. Swan & Co. When 1878 12
NET 1235 Owners Christie & Co. Port belonging to London
GROSS 1895

UNDER DK. 1807 Owners' Address
If Surveyed Afloat or in Dry Dock Afloat Name of Dock Victoria Destined Voyage Vera Cruz
Length of Poop ft. of Forecastle ft. of Raised Or. Deck ft. Moulded Depth ft. ins.
(if these particulars are not yet recorded in the Register Book.)

Last Survey, No. 7991 Port April
Classed L.M.C. 7.88 100 A 1
+ N.B. 88 12.89
S. S. No. 3 Sec. 7.88

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard } in Summer ft. ins.
Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned)
of any letters respecting this case.) as painted on Ship } in Winter ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Auditum
This Vessel has been visited afloat in the Victoria Dock, and a Kedge
Anchor has now been supplied with Certificate of Test of which the following
are particulars. — No. of Certificate 7354, Low Walker 10th October 1882,
Iron Staked 5.2.7, Stalk 1.1.0, Proof strain 7.18.1.21, Mark 3.81.
W.P. required by Rule 5.1.0
L.P.H. - L.W. B & T. Maker's name John Abbot & Co. (Sgl) Robert Burrell, Esq.

PRESENT CONDITION OF THE		Plank (Bottom) & Counter	Ceiling	Boats
Decks	prd	not seen	where seen prd	4 prd
Waterways	"	Treenails or Rivets	not seen	Masts, Yards, &c.
Comings	"	Breasthooks & Stemson	not seen	Condition, how ascertained
Up'r Dk. Beams & Fastenings	where seen prd	Transoms, Pointers, & Crutches	not seen	Sails
Low'r Dk. Beams & Fastenings	prd	Timbers of Frame at the openings	not seen	Anchors No. of 3 B, 1 S, 2 K
Plank sheers	prd	Ditto ditto at other places	not seen	Cables Stated to be complete
Sheerstrakes	"	Keelsons	Caulking of Bot'm, D'k, & Wat'rways prd	Hawsers & Warps
Topsides	"	Clamps & Shelves	Copper, or Y.M. (State if on Felt.) When put on	Standing & Running Rigging
Wales	"			Hatches
Engine Room Skylights	prd	Coal Bunker, Openings, Lids, &c	Scuppers prd	Cargo & Main Hatchways

General Observations, Opinion as to Class, Recommendation, &c. :
The Vessel, so far as seen, is in a sound and efficient condition, and
eligible in my opinion to remain as classed, without fresh survey
of survey.

Entry Fee (if chargeable) per Scale I., Sec. 27...	£		Fees applied for,
Office Fee (if chargeable) per Scale II., Sec. 27...	£		18
Survey Fee (per Section 28)	£		Received by me,
Special on Damage, Fee (if any) (per Sec. 28) ...	£		18
*Certificate (if required) to be sent as per margin	£		
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute 100 A 1 on April Rep No. 7991
Character assigned
16 MAY 1890
Surveyor to Lloyd's Register of British & Foreign Shipping.
© 2019 Lloyd's Register Foundation