

REPORT of SURVEY for REPAIRS, &c.

Received in London Office,

WED 10

1890

No.

Date of Writing Report

18

Port of

No. in
Reg. Book.

Survey held at

London

Date, First Survey

(No. of Visits)

26 July

Last Survey

4 Sept

1890.

2556

on the

Wh. Auriga

Master

G. Stone

YEAR.

MONTH.

TONNAGE:-

NET

284 518

Built at

Sunderland

By whom

Cliff Ramsey

When

1869

9

GROSS

919 540

Owners

Keith Ramsey

Port belonging to

Dunedin

UNDER DK.

825 499

Owner's Address

Dunedin.

If Surveyed Afloat or in Dry Dock

Dry Dock

Name of Dock

Commercial

Destined Voyage

Hobart

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft.

ins.

(if these particulars are not yet recorded in the Register Book.)

Years assigned, if a Wood Ship.

Character in Register Book.

Last Survey, No.

1897 40

Port

Classed

S.S. Lon. No 3-12.82

S.S. Lon. No 1-86

*A1

7.89

ft. 02 ins.

ft. ins.

(State clearly the cause of Repairs if any, and in detail the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be segregated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

Society's Freeboard

in Summer

3

ft. 02 ins.

as painted on Ship

in Winter

ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR S.S. No 2.

This vessel has now been placed in dry dock & prepared for this survey by the removal of ceiling, considerably in excess of the rule requirements.

The iron surfaces thus exposed have been cleaned, sealed, & recoated. The cement, except in a few spaces which have now been made good, was found to be in a satisfactory condition. Sunday small repairs have been done to hold beams, & several rivets in peak bulkhead renewed.

Parts of eight strakes of main deck, being worn somewhat thin, have now been renewed, & the deck recaulked where necessary.

Masts, spar, & equipment generally have been overhauled and made good, the chain cables rapped and found complete.

The bottom has now been cleaned & recoated.

Four topsail yards renewed. Considerable quantity of ceiling renewed.

PRESENT CONDITION OF THE

Decks	gnd	Plank (Bottom) & Counter	gnd	Ceiling	gnd	Boats	gnd
Waterways	"	Trussings or Rivets	gnd	Rudder	"	Masts, Yards, &c.	gnd
Comings	"	Breasthooks and Stemson	"	Windlass & Capstan	"	Condition, how ascertained	inspection
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"	Sails	gnd
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the opening	"	Cement (if Iron Ship)	"	Anchors No. of	3 B. 15. 2 K.
Plank sheers	"	Ditto ditto at other places	"	Caulking of Bot'm, D'k, & Wat'rways	"	Cables	rapped complete
Sheerstrakes	Plating	Keelsons	"	Copper or V.M.	"	Hawsers & Warps	gnd
Topsides	"	Clamps & Shelves	"	(State if on shell.)	"	Standing & Running Rigging	"
Wales	"			When put on	"	Hatches	"
Engine Room Skylights	"	Coal Bunker, Openings, Lids, &c.	"	Scuppers	gnd	Cargo & Main Hatchways	gnd

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel is in gnd condition, eligible, in my opinion, to remain as classed & to be marked S.S. Lon. No 2-90. with date of last survey

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:
Survey Fee (per Section 28)	£	4	10
Special on Damage, Fee (if any) (per Sec. 28)...	£	:	:
*Certificate (if required) to be sent as per margin	£	:	5
Travelling Expenses (if chargeable)	£	:	:
Second Surveyor's Fee (if any)	£	:	10

Fees applied for,

19/1890

Received by me,

10/9/90

10/9/90

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

FRI 12 SEPT 1890

*A1

S.S. No 2-90

ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 18, Old Street, Goswell Road, London.

Lloyd's Register Foundation

LON 690-0445

State if a Report is also sent on the Machinery of the Ship or if not whether, and when, one will be so.

* Certificate to be sent to

Form No. 2 for Repairs-10000-21 3/90-(Transfer Ink-T & S.) The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.