

REPORT of SURVEY for REPAIRS, &c.

No. *648* Date of Writing Report *19 Mar 1891* Port of *London* Received in London Office, *5 16 80*
 No. in Reg. Book. *648* Survey held at *London* Date, First Survey *18 Mar* Last Survey *18 Mar 1891*
 on the *Stub s/s "Somerhill"* (No. of Visits *1*) Master *Richardson Duck*

TONNAGE:—
 NET *1498* Built at *Stockton* By whom *Richardson Duck* When *1888* YEAR. MONTH.
 GROSS *2274* Owners *S. S. Somerhill & Co* Port belonging to *London*
 UNDER DK. *1746* Owners' Address
 (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Name of Dock *Cape Inn* Destined Voyage *Cape Inn*
 Length of Poop *ft.:* of Forecastle *ft.:* of Raised Qr. Deck *ft.:* Moulded Depth *ft.* ins.
 (if these particulars are not yet recorded in the Register Book.)

Last Survey, No. *8357* Port *Hpl* Classified *4 Smc - 1, 88*
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned) in Summer *ft.* ins.
 of any letters respecting this case. as painted on Ship in Winter *ft.* ins.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Equipment*
The two seven inch ropes and the wire rope referred to in the Harlepool report are not on board.

PRESENT CONDITION OF THE			
Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks & Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Planksheers	Ditto ditte at other places	Caulking of Bot'm, D'k, & Watrways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			Hatches
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways

General Observations, Opinion as to Class, Recommendation, &c.: *As far as seen this vessel was appear eligible to remain as classed without fresh record of survey*

Entry Fee (if chargeable) per Scale I., Sec. 27...	£	:	:	Fees applied for, 18 Received by me, 18
Office Fee (if chargeable) per Scale II., Sec. 27...	£	:	:	
Survey Fee (per Section 28)	£	:	:	
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:	
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute
 Character assigned *See minute on Hpl Rpt No 8357*

W. L. Gray
 Surveyor to Lloyd's Register of British & Foreign Shipping.
 FEB 20 MAR 1891
 Lloyd's Register Foundation
 LON 692-0259

State if a Report is also sent on the Machinery of the Ship or if not whether, and when, one will be sent.

Form No. 2 for Repairs—1000—21, 530.—Transfer 1 k.—T. & S.
 (The Surveyors are requested not to write on or below the space for Committee's Minutes.)

Insert Character precisely as in Register Book.