

No. 52453

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report Feb 5th 1892 When handed in at Local Office

Port of London SAT. 6 FEB 1892

No. in Survey held at London

Date, First Survey Feb 2nd Last Survey Feb 2nd 1892

Reg. Book.

153 - on the Steel Tug Se. "Bazalgette".

Master C. Liveash.

YEAR. MONTH.

TONNAGE:-

GROSS 999

UNDER DK. 967

NET 613

Built at Barrow.

By whom Brw. S.B.C. (Lim.) When 1887. 5.

Owners London County Council

Port belonging to London

Owners' Address

(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Afloat Name of Dock off Beckton. Destined Voyage

WB=DbA tons; f tons; uE&B tons; CellDB tons; FPT tons; APT tons; MT tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Years Assigned now or expired.	Machinery and Boiler Surveys (including date of N.B., if any).
✱ 100. A. ✱	—	✱ L.M.C. 10.91.
9.90.		

Last Survey, No. 52453 Port Lon.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of S.S. 10th 1.

London Report No. 52453. dated November 10th 1891. states that in order to complete the S.S. 10th 1. the Coal Bunkers require to be cleared and examined. This has now been done, and the timbers lifted according to rule, and the cement examined and the whole found in good order.

SUMMARY OF DAMAGE REPAIRS: — Plates, Paired or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE

Decks	Good	Transoms, Pointers, & Crutches	✓	Copper, or Y.M.	✓	Hatches	Good
Waterways	✓	Timbers of Frame at the openings	Parts	(State if on Felt.)	✓	Boats	✓
Coamings	✓	Ditto ditto at other places	seen	When put on, Month	✓	Masts, Yards, &c.	✓
Up'r Dk. Beams & Fastenings	✓	Keelsons	good	Rudder	As seen	Condition, how ascertained	From SK
Low'r Dk. Beams & Fastenings	✓	Clamps, Shells & Stringers	good	Windlass & Capstan	Good	Sails	✓
Plating	As seen	Salting	✓	Pumps	✓	Anchors No. of	313 15. 24
Planking	✓	Ceiling	Good	Engine Room Skylights	✓	Cables, length	Stated complete
Treenails or Rivets	✓	Cement or Asphalt (State which.)	Cement	Coal Bunker, Open'gs, Lids, &c.	✓	(State if now ranged)	No.
Breasthooks & Stemson	✓	Tanks (State if now tested.)	✓	Scuppers	✓	Hawser & Warps	Good
		Caulking of Bot'm, D'k, & Wat'rw'ys	✓	Cargo & Main H'tch'w'ys	✓	Standing & Running Rigging	✓

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel appears in good and efficient condition and eligible in my opinion to remain as classed, and to have the notation S.S. Lon. 10th 1. 91.

Office Fee (if chargeable) per Scale II., Sec. 27	£	:	:	Fees applied for,
Survey Fee (per Section 28)	£	:	:	18.
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	18.
Second Surveyor's Fee (if any)	£	:	:	


*Is Certificate now required?

Committee's Minute

FRI 12 FEB 1892

Character assigned

Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation

LON695-0210

Is a Report also sent now on the Machinery of the Ship? If not, state whether, and when, one will be sent?

* Certificate to be sent to

Form No. 3 for Repairs—295—L.R.P.H.—20,000.—249/91.—(Transfer Ink.)
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

N.B.—All alterations in the existing records should be underlined.