

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 23-1-94 When handed in at Local Office 23-1-94 Port of London

No. in Reg. Book 374 Survey held at London Date, First Survey 18/1/94 Last Survey 23-1-1894 on the Wood, Iron or Steel 2/8 Drummond Castle Master Roman 92-92

TONNAGE:- Built at Glasgow By whom Gleaner Coy When 1881-2 GROSS 3663 Owners D. Currie Coy Port belonging to London UNDER DK. 3537 Owners Address Owners Address (if not already recorded in Register Book.) NET 2352

Surveyed Afloat or in Dry Dock? In Dry Dock Name of Dock S. Dock Destined Voyage Cape

WB=DbA tons; f tons; uE&B tons; CellDB tons; FPT tons; APT tons; MT tons. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey, No. 55096 Port Lon + 100A-1. + TL 13 10/87 10/93 + DL 13 3/93

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Temporary Repairs of Damage Sustained through striking the Quay Wall of the East India Dock.

On the starboard side:- The stem plate of an outside strake was fractured - 8" strake below the sheer, and covered by a rivetted plate patch. Similarly on the port side a breast of foremast, one plate in the 3rd & 4th strake below sheer were indented and fractured - a doubling plate patch was rivetted over damaged landing edges of these plates

SUMMARY OF DAMAGE REPAIRS :- Plates, Faired or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE		Copper or Zinc (State if on form. When put on, Month)		Hatches	
Decks	Good	Transoms, Pointers, & Crutches	Good	Hatches	Good
Waterways	"	Timbers of Frame at the openings	"	Boats	"
Coamings	"	Ditto ditto at other places	"	Masts, Yards, &c.	from Dk
Up'r Dk. Beams & Fastenings	"	Keelsons	"	Condition, how ascertained	from Dk
Low'r Dk. Beams & Fastenings	"	Clamps, Shelves & Stringers	"	Sails	20 good
Plating	"	Decking (State if examined.)	"	Equipment letter	20 good
Rivets	"	Ceiling	"	Anchors, No. of	3/3-15-2K
Breasthooks & Stowage	"	Cement or Asphalt (State which.)	"	Cables (State if now ranged)	" length size Rule length
		Tanks (State if now tested.)	"	Hawsers & Warps	good
		Caulking of Bot'm, D'k, & Wat'r'ys	"	Standing & Running Rigging	"

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and pND91, &c."

This vessel now appears to be in a sound and efficient condition. eligible in our opinion to remain as classed. subject to the damage being made good on her return to the V.K. no record of survey when made

Office Fee (if chargeable) per Scale I., Sec. 2 Survey Fee (per Section 25) Special Damage or Repair Fee (if any) Travelling Expenses (if chargeable) Second Surveyor's Fee (if any) Fees applied for, Received by me, Surveyor to Lloyd's Register of British & Foreign Shipping.

Character assigned Deferred for permanent repairs

Form No. 2 for Repairs - 2/45, R.P.H. - 10,000 - 25, 10/93. - Transfer Ink. (The Surveyors are requested not to write on or below the space for Committee's Minute.) \* Certificate, if required, to be sent to

