

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 2<sup>nd</sup> April 1894 When handed in at Local Office

18

Port of London

No. in  
Reg. Book.

Survey held at London

Date, First Survey 28<sup>th</sup> Mar

Last Survey 29<sup>th</sup> Mar 1894

(No. of Visits

Master Griffith

170 on the Wood Iron or Steel S.S. "Manitoba"

TONNAGE:—

Built at Belfast

By whom Harland & Wolff

When 1892

YEAR.

GROSS 5672

Owners

Williams, Torrey and Field

Port belonging to London

UNDER DK. 5294

Owners Address

NET 1653

(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock

5.9K Name of Dock

R.A.D. OK

Destined Voyage St. York

WB=DBa

tons; f

tons; uE&B

tons; CellDB

tons; FPT

tons; APT

tons; MT

tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.  
\* for Special Survey.  
Date of last Survey and of  
Periodical Surveys

Machinery and Boiler  
Surveys  
(including date of N.B., if any).

Last Survey, No. 55230

Port Lon

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as 8 ft 10 1/2 ins. painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey

Keel and bottom examined in dry dock, two plates just above the garb on the port bow slightly indented, and a number of rivets in way of same, started. Three rivets now cut out and renewed, and cement in way of same made good, a few rivets also renewed in the shell plating on the starboard bow, and bottom cleaned and recoated.

SUMMARY OF DAMAGE REPAIRS:— ☒ Plates, Faired or Repaired; ☒ Frames, ditto. ☒ Plates, Renewed; ☒ Frames, ditto. Other Repairs ☒

PRESENT CONDITION OF THE

Decks <u>Good</u>	Transoms, Pointers, & Crutches <u>Good</u>	Copper or V.M. <u>Good</u>	Hatches <u>Good</u>
Waterways <u>Good</u>	Timbers of Frame at the openings <u>Good</u>	(State if on Hull) When put on, Month <u>Year</u>	Boats <u>Good</u>
Coamings <u>Good</u>	Ditto ditto at other places <u>Good</u>	Rudder <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Up'r Dk. Beams & Fastenings <u>Good</u>	Keelsons <u>Good</u>	Windlass & Capstan <u>Good</u>	Condition, how ascertained <u>See from St</u>
Low'r Dk. Beams & Fastenings <u>Good</u>	Clamps, Shells & Stringers <u>Good</u>	Pumps <u>Good</u>	Sails <u>Good</u>
Plating <u>Good</u>	Siding <u>Good</u>	Engine Room Skylights <u>Good</u>	Equipment letter <u>at</u>
Flanking <u>Good</u>	(State if examined.) <u>Good</u>	Coal Bunker, Open'gs, Lids, &c. <u>Good</u>	Anchors, No. of <u>410. 10. 2K</u>
Ironwork or Rivets <u>Good</u>	Cement on Asphalt <u>Good</u>	Scuppers <u>Good</u>	Cables (State if now ranged) <u>no</u>
Breasthooks & Stemson <u>Good</u>	(State which) <u>Good</u>	Cargo & Main H'tch'ys <u>Good</u>	" length <u>—</u> size <u>—</u>
	Tanks <u>Good</u>		" Rule length <u>—</u> size <u>—</u>
	(State if now tested.) <u>Good</u>		Hawsers & Warps <u>Good</u>
	Caulking of Bot'm, D'k, & Wat'r'ys <u>Good</u>		Standing & Running Rigging <u>Good</u>

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1,991 and ptND91, &c."

This vessel is now in good and efficient condition, and eligible to remain as Classed, with record 3.94.

Office Fee (if chargeable) per Stat II., Sec. 27 £

Survey Fee (per Section 25) £

Special Damage or Repair Fee (if any) (per Sec. 25.) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

\*Is Certificate now required?

Fees applied for,

18

Received by me,

18

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

FRI 6 APR 1894

100A



© 2019

Lloyd's Register Foundation

LON701-0410