

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 25 April 94 When handed in at Local Office 18

Port of London

No. in
Reg. Book.

Survey held at London

Date, First Survey 30 March Last Survey 9 April 1894

16 on the Wood, Iron or Steel S. S. Nairnshire

(No. of Visits 5)

Master Olsen

YEAR. MONTH.

TONNAGE:-

GROSS 3720

UNDER DECK 3076

NET 2428

Built at Newcastle

By whom R. & W. Hawthorn & Co When 1889. 8

Owners Turnbull, Martin & Co

Port belonging to Glasgow

Owners' Address

(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? D. 9K Name of Dock Thomas S. Wain Destined Voyage Sydney.

WB=DBa ✓ tons; f ✓ tons; uE&B ✓ tons; CellDB ✓ tons; FPT ✓ tons; APT ✓ tons; MT ✓ tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Year Assigned	Machinery and Boiler Surveys (including date of N.B., if any).
✓ for Special Survey. Date of last Survey and of Periodical Surveys.		
*100 A 1 4.93	✓	2. M. C. 10. 93

Last Survey, No. 54854 Port London

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

Society's Freeboard (if assigned) as painted on Ship and now verified 3 ft. 11 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Part S. S. No 1. See London Report No 54854.

Steel and bottom examined in dry dock, and the bottom cleaned and recoated; The Water ballast tanks satisfactorily tested by water pressure, and the plating, frames, stringers &c in the after hold cleaned and recoated above the close ceiling.

To complete the Survey the after lower cross bunker to be cleared and examined; notice of which has been given to the owners, who state this will be done on her return.

SUMMARY OF DAMAGE REPAIRS: — ✓ Plates, Fair'd or Repaired; ✓ Frames, ditto. ✓ Plates, Renewed; ✓ Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE

Decks	Transoms, Pointers, & Crutches	Copper or T.M.	Hatches
Good	Good	(State if on Rail.)	Good
Waterways	Timbers of Frame at the openings	When put on, Month	Boats
Coamings	Ditto ditto at other places	Year	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings	Keelsons	Rudder	Condition, how ascertained
Low'r Dk. Beams & Fastenings	Clamps, Shells & Stringers	Windlass & Capstan	Sails
Plating	Salting	Pumps	Equipment letter
Docking	(State if examined.)	Engine Room Skylights	Anchors, No. of
Frames or Rivets	Ceiling	Coal Bunker, Open'gs, Lids, &c.	Cables (State if now ranged)
Breasthooks & Stemson	Cement or Asphalt	Scuppers	" length size
	(State which.)	Cargo & Main H'tch'ys	" Rule length size
	Tanks		Hawsers & Warps
	(State if now tested.)		Standing & Running Rigging
	Caulking of Bot'm, D'k, & Wat'r'ys		

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and pEND91, &c."

This vessel is now in good and efficient condition, and eligible to remain as Classed, without fresh record of Survey.

Office Fee (if chargeable) per Section II., Sec 27	£	Fees applied for,
Survey Fee (per Section 29)	£	18
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	Received by me,
Travelling Expenses (if chargeable)	£	18
Second Surveyor's Fee (if any)	£	

*Is Certificate now required?

Committee's Minute

Character assigned

TUES. 17 APR 1894

Deferred for Comple. of No. 1

TUES. 16 OCT 1894

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register Foundation

LON 701-0454