

It is submitted that
this vessel is eligible for
THE RECORD B.S. 7-94

N.A.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

7-7-94
On Oct 4th of last year
a small repair was
effected to the D Bank.

N.A.
7-7-94

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation