

(Received at London Office MON. 1 OCT 1894)

No. 55883

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 28th Sep 1894 When handed in at Local Office 18 Port of London

No. in Reg. Book. Survey held at London Date, First Survey 12th Sep Last Survey 25th Sep 1894

417 on the Wood, Iron or Steel S.S. Northwood Master

TONNAGE:— Built at Newcastle By whom Palmers & Co When 1889.1

GROSS 710 Owners Fenwick & Co Port belonging to London

UNDER DK. 549 Owners' Address

NET 345 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? D. 94 Name of Dock Orchard Destined Voyage Cruising.

WB=DbA tons; f tons; uE&B tons; CellDB tons; FPT tons; APT tons; MT tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 54427 Port Hon

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage repairs caused by Collision. Shot and Bottom examined

in dry dock, on the Port bow two shell plates removed, faired and repaired, and three other shell plates faired in place, two frames repaired, one bulwark plate on the port side aft renewed, and rails repaired. The bottom cleaned and recrated.

SUMMARY OF DAMAGE REPAIRS:—5 Plates, Faired or Repaired; 2 Frames, ditto. 1 Plates, Renewed; 1 Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE		Hatches	
Decks	Good	Boats	Good
Waterways	Good	Masts, Yards, &c.	Good
Coamings	Good	Condition, how ascertained	See from
Up'r Dk. Beams & Fastenings	Good	Sails	Good
Low'r Dk. Beams & Fastenings	Good	Equipment letter	K
Plating	Good	Anchors, No. of	3 B. 1 B. 2 R
Flanking	Good	Cables (State if now ranged)	No
Transoms or Rivets	Good	length	size
Breasthooks & Stemson	Good	Rule length	size
Transoms, Pointers, & Crutches	Good	Hawsers & Warps	Good
Timbers of Frame at the openings	Good	Standing & Running Rigging	Good
Ditto ditto at other places	Good		
Keelsons	Good		
Clamps, Shells & Stringers	Good		
Salting (State if examined.)	Good		
Ceiling	Good		
Cement or Asphalt (State which.)	Good		
Tanks (State if now tested.)	Not tested		
Caulking of Bot'm, D'k, & Wat'r'ys	Good		
Copper, or Y.M. (State if on roll.)	Good		
When put on, Month	Good		
Rudder	Good		
Windlass & Capstan	Good		
Pumps	Good		
Engine Room Skylights	Good		
Coal Bunker, Open'gs, Lids, &c.	Good		
Scuppers	Good		
Cargo & Main H'tch'ys	Good		

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel is now in good and efficient condition, and eligible to remain as Classed with record 9.94.

Office Fee (if chargeable) per Scale II, Sec. 27	£	Fees applied for,	18
Survey Fee (per Section 29)	£	Received by me,	18
Special Damage or Repair Fee (if any) (per Sec. 28.)	£		
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

*Is Certificate now required?

Committee's Minute TUES. 9 OCT 1894

Character assigned 100A

Surveyor to Lloyd's Register of British & Foreign Shipping.

© 2019 Lloyd's Register Foundation

Law 703 - 0229