

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 28th Sep 1894 When handed in at Local Office 18th Port of London

No. in Survey held at London Date, First Survey 26th Sep^r Last Survey 27th Sep^r 1894
Reg. Book. (No. of Visits) 2 Master Harris

847 on the Wood, Iron or Steel S.S. "Spheroid" Built at W. Hartlepool By whom A. Gray & Co. When 1891 12

TONNAGE:- GROSS 1941. Owners Scrutton Sons & Co. Port belonging to London
UNDER DK. 1787. Owners' Address (if not already recorded in Appendix to Register Book.)

NET 1238. Surveyed Afloat or in Dry Dock? Name of Dock Green Dry Dock Destined Voyage Guadeloupe

WB=DbA tons; f tons; uE&B tons; CellDB tons; } Particulars of Classification (which must be inserted
FPT tons; APT tons; MT tons. } precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 122969 Port London

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey.
Vessel placed in dry dock, bottom examined cleaned and painted.

SUMMARY OF DAMAGE REPAIRS:—Plates, Fair'd or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE		Plating		Copper, or Y.M.		Hatches	
Decks	Good	Transoms, Pointers, & Crutches	hot seen	(State if on Felt.)	✓	When put on, Month	Year
Waterways	"	Timbers of Frame at the openings	Good	Rudder	Good	Boats	"
Coamings	"	Ditto ditto at other places	hot seen	Windlass & Capstan	"	Masts, Yards, &c.	"
Up'r Dk. Beams & Fastenings	"	Keelsons	Part seen Good	Pumps	"	Condition, how ascertained	From dk
Low'r Dk. Beams & Fastenings	"	Clamps, Shelves & Stringers	"	Engine Room Skylights	"	Sails	"
Plating	"	Sanding	"	Coal Bunker, Open'gs, Lids, &c.	"	Equipment letter	"
Planking	"	Cement or Asphalt	hot seen	Scuppers	"	Anchors, No. of	30: 15: 2K
Trussing or Rivets	"	Tanks	"	Cargo & Main H'tch'w'ys.	"	Cables (State if now ranged)	ho
Breasthooks & Breeches	hot seen	Caulking of Bot'm, D'k, & Wat'r'w'ys.	Good			" length	size
						" Rule length	size
						Hawsers & Warps	Good
						Standing & Running Rigging	"

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel, so far as seen, is now in good and efficient condition and eligible in my opinion to remain as classed with record of survey "9,94"

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fees applied for,	
Survey Fee (per Section 25)	£	18	
Special Damage or Repair Fee (if any) (per Sec. 25.)	£	Received by me,	
Travelling Expenses (if chargeable)	£	18	
Second Surveyor's Fee (if any)	£		

*Is Certificate now required? _____

Committee's Minute TUES. 9 OCT 1894

Character assigned ✓ 100A1 Spar dk.

Form No. 2 for Repairs—205—5000.—10/7/94.—Transfer Ink.—The Surveyors are requested not to write on or below the space for Committee's Minute.

