

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 6/5/95 When handed in at Local Office 6/5/95 Port of London

No. in Survey held at London Date, First Survey 254-95 Last Survey 6-5-1895

Reg. Book. 473 on the Wood, Iron or Steel Brackadder. (No. of Visits 5 Master J. Grassam

TONNAGE:- Built at London By whom Maudslays & Sons When 1870-2

GROSS 970 Owners J. Willis & Son Port belonging to London

UNDER DEK. 872 Owners Address

NET 917 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Limehouse Dock Destined Voyage Brisbane

WB=Deba tons; f tons; uE&B tons; CellDB tons; FPT tons; APT tons; MT tons. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 554 73 Port Lon

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This vessel was seen lying in Limehouse Dock. The bottom examined cleaned & coated. The rudder lifted and pintles bushed. The deck under Galley stove partly renewed.

SUMMARY OF DAMAGE REPAIRS:—Plates, Fair'd or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE	Doubling Plates under Sounding Pipes	not seen	Transoms, Pointers, & Crutches	Good	Copper, or F.M.	Hatches	Good
Decks	Good		Plates of Frame at the openings		(State if on Felt.)	Boats	
Waterways			ditto at other places		When put on, Month	Masts, Yards, &c.	
Coamings			Keelsons		Year	Condition, how ascertained	from Dk
Up'r Dk. Beams & Fastenings			Openings, Shells & Stringers			Sails	good
Low'r Dk. Beams & Fastenings			Plating (State if examined.)			Equipment letter	
Plating			Ceiling			Anchors, No. of	313-18-215
Painting			Cement on Deck			Cables (State if now ranged)	no
Iron or Rivets			Teak (State if examined.)			"length	stated complete
Breasthooks & Stem			Caulking of Bot'm, D'k, & Wat'rw'ys			"Rule length	size
						Hawsers & Warps	good
						Standing & Running Rigging	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel now appears to be in a sound & efficient condition, eligible in my opinion to remain as classed with a last date of survey Lon 595.

Office Fee (if chargeable) per Scale II., Sec. 27 £

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) (per Sec. 28.) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for, 18

Received by me, 18

Is Certificate now required?

Committee's Minute

Character assigned

FRI 10 MAY 1895

Edward Ford Siemey

Surveyor to Lloyd's Register of British & Foreign Shipping.

LON 705-0140

© 2019 Lloyd's Register Foundation