





56750 For

one bent - These have now been repaired & the gear  
overhauled The rudder has been bushed

The bottom is now in good condition & has been  
cleaned & coated

ACK

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation