

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 31st Aug 96 When handed in at Local Office 18 Port of London

No. in Reg. Book 84 Survey held at London Date, First Survey 24th Aug 93 Last Survey 28th Aug 96
on the Wood, Iron or Steel S. S. Warrigal Master Pennkethurst

TONNAGE Built at Sunderland By whom Sam Ship B. C. (Lm), When 1893. 8
GROSS 4387 Owners H. Lm. Port belonging to London
UNDER DK 4036 Owners' Address
NET 2778 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? 2. 96 Name of Dock Greens Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; }
total capacity - tons. FPT - tons; APT - tons; MT - feet . tons. }
N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 57441 Port Lon

(Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey.

Steel and bottom examined in dry dock, and the bottom cleaned and recoated.

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed ...								
Faired or Repaired ...								
PRESENT CONDITION OF THE	Timbers of Frame at the openings	Rudder	Hatches					
Decks	Ditto ditto at other places	Windlass & Capstan	Boats					
Waterways	Keelsons	Have Pumps now been examined and found efficient?	Masts, Yards, &c.					
Coamings	Stringers, Clamps & Shells	Have Sluice Valves now been examined and found efficient?	Condition, how ascertained					
Up'r Dk. Beams & Fastenings	Siding (State if examined.)	Have Watertight Doors now been examined and found efficient?	Sails					
Low'r Dk. Beams & Fastenings	Ceiling	Dblng. Plates under Sounding Pipes	Equipment letter					
Plating	Cement or Asphalt (State which.)	Engine Room Skylights	Anchors, No. of					
Blanking	Tanks (State if now tested.)	Coal Bunker, Open'gs, Lids, &c.	Cables (State if now ranged)					
Rivets or Screws	Caulking of Bot'm, D'k, & Wat'rw'ys	Scuppers	" length (on board)					
Breasthooks & Stemson	Copper, or T.M. (State if on Bolt.)	Cargo & Main H'tch'w'ys	" Rule length (per Table 22)					
Transoms, Pointers, & Crutches	When put on, Month		Hawsers & Warps					
			Standing & Running Rigging					

General Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel is now in good and efficient condition, and eligible to remain as classed, with record 8. 96.

Office Fee (if chargeable) per Scale II., Sec. 27 £ : : Fees applied for, 18.
Survey Fee (per Section 28) £ : : Received by me, 18.
Special Damage or Repair Fee (if any) (per Sec. 28.) £ : :
Travelling Expenses (if chargeable) £ : :
Second Surveyor's Fee (if any) £ : :

Committee's Minute
Character assigned