

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18 When handed in at Local Office 18 Port of London

No. in Survey held at London Date, First Survey Dec 12 Last Survey 15/12 1896
Reg. Book. 866 on the Wood, Iron or Steel S.S. Southern Cross Master A. Child
(No. of Visits 2)

TONNAGE:-
GROSS 5050 Built at Belfast By whom Workman Clark When 1892-9
UNDER DECK 4932 Owners Southern Cross S.S. Co Port belonging to London
NET 3311 Owners' Address

Surveyed Afloat or in Dry Dock? Name of Dock W. J. Drake Destined Voyage Havre

WB=CellDBorDBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. X for Special Survey. Date of last Survey and of Periodical Surveys. Years Assigned expired. Machinery and Boiler Surveys (including date of N.B., if any).
+100A1 ✓ +LMC992
2.96 ✓

Last Survey, No. 57845 Port Lon
Society's Freeboard (if assigned) as painted on Ship and now verified 7 ft. 3 ins. ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage. S.S. N°1 partly held on account of damage by heavy weather, the windlass has been repaired.

Sundry small deck damages will be made good on the vessel's return in next week, when the Owners propose to further the S.S. N°1, which is partly held

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Faired or Repaired ...								

PRESENT CONDITION OF THE	Timbers of Frame at the openings	Rudder	Hatches
Decks	Ditto ditto at other places	Windlass & Capstan Good	Boats
Waterways	Keelsons	Have Pumps now been examined and found efficient?	Masts, Yards, &c.
Coamings	Stringers, Clamps & Shells	Have Sluice Valves now been examined and found efficient?	Condition, how ascertained (State if wedges removed)
Up'r Dk. Beams & Fastenings	Salting (State if examined.)	Have Watertight Doors now been examined and found efficient?	Sails
Low'r Dk. Beams & Fastenings	Ceiling	Dblg. Plates under Sounding Pipes	Equipment letter
Plating	Cement or Asphalt (State which.)	Engine Room Skylights	Anchors, No. of
Planking	Tanks (State if now tested.)	Coal Bunker, Open'gs, Lids, &c.	Cables (State if now ranged)
Rivets or Treennails	Caulking of Bot'm, D'k, & Wat'rw'ys	Scuppers	" length (on board) size
Breasthooks & Stemson	Copper or Y.M. (State if on Felt.)	Cargo & Main H'tchw'ys	" Rule length (per Table 22) size
Transoms, Pointers, & Crutches	When put on, Month Year		Hawsers & Warps
			Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c. :-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel's windlass has now been repaired. She is eligible in my opinion to remain as classed without fresh record of Survey.

Office Fee (if chargeable) per Scale II., Sec. 27	Fees applied for,
Survey Fee (per Section 28)	18
Special Damage or Repair Fee (if any) (per Sec. 28.)	Received by me,
Travelling Expenses (if chargeable)	18
Second Surveyor's Fee (if any)	

Committee's Minute FRI 1 JAN 1897 FRI 15 JAN 1897 FRI 23 APL 1897 TUES, 28 SEP 1897
Character assigned Defered for completion of No. 1
No. 1 st
D. Truck Moore
Surveyor to Lloyd's Register of British & Foreign Shipping.
Lloyd's Register Foundation
LON711-0205

If a Report also sent now on the Machinery of the Ship If not, state whether, and when, one will be sent

Is Certificate required? If so to be sent to