

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 15 Oct 1897. When handed in at Local Office 18 Port of London

No. in Reg. Book 176 Survey held at London Date, First Survey 7 Oct Last Survey 7 Oct 1897

on the Wood, Iron or Steel S.S. "Hawarden Castle" Master Rigby

TONNAGE:- Built at Glasgow By whom J. Elder & Co When 1883 1

GROSS 4380 Owners (S. Currie & Co.) Port belonging to London

UNDER DEK 4012 Owners' Address (if not already recorded in Appendix to Register Book.)

NET 2556 Surveyed Afloat or in Dry Dock? Name of Dock Thames Dry Dock Destined Voyage Cape Town

WB=CellDBorDBa feet; uE&B feet; f feet; Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

total capacity tons. FPT tons; APT tons; MT feet tons. Machinery and Boiler Surveys (including date of N.B., if any).

N.B.—All alterations in the existing records should be underlined. Last Report, No. 59048 Port London

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

CHARACTER. For Special Survey. Date of last Survey and of Periodical Surveys. Years Assigned now expired. Machinery and Boiler Surveys (including date of N.B., if any).

Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition Vessel placed in dry dock bottom examined cleaned and painted.

Table with columns: Plates, Frames, R. Frames, Floors, Beams, Str. Plates, Dk. Plates, Other Items. Rows for Renewed and Faired or Repaired.

Table with columns: Decks, Waterways, Coamings, Up'r Dk. Beams & Fastenings, Low'r Dk. Beams & Fastenings, Plating, Planking, Rivets or Treennails, Breasthooks & Stems, Transoms, Pointers & Crutches, Timbers of Frame at the openings, Keelsons, Stringers, Clamps & Shells, Salting, Ceiling, Cement or Asphalt, Tanks, Caulking of Bot'm, D'k, & Wat'r'ys, Copper, or Y.M., When put on, Month, Year, Rudder, Windlass & Capstan, Have Pumps now been examined and found efficient?, Have Sluice Valves now been examined and found efficient?, Have Watertight Doors now been examined and found efficient?, Dhng. Plates under Sounding Pipes, Engine Room Skylights, Coal Bunker, Open'gs, Lids, &c., Scuppers, Cargo & Main H'tch'ys, Hatches, Boats, Masts, Yards, &c., Condition, how ascertained, Sails, Equipment letter, Anchors, No. of, Cables (State if now ranged), length, size, Rule length, size, Hawsers & Warps, Standing & Running Rigging.

### General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,97," or "to remain as classed and to have record of survey, 1,97, and the notations of ss No. 1-97 and pEND97, &c."

This vessel, as far as seen, is now in good and efficient condition and eligible in my opinion to remain as classed with record of survey 10-97

Table with columns: Office Fee, Survey Fee, Special Damage or Repair Fee, Travelling Expenses, Second Surveyor's Fee, Fees applied for, Received by me.

Committee's Minute Character assigned Referred for ps.

FRI. 22 OCT 1897 FRI. 12 AUG 1898 FRI. 21 JAN 1898 FRI. 13 MAY 2019 Lloyd's Register Foundation

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

Is Certificate required? If so to be sent to