

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 17th Feb 1898 When handed in at Local Office 18 Port of London
No. in Reg. Book 97 Survey held at London Date, First Survey 2nd Jan Last Survey 12th Dec 1897
on the Wood, Iron or Steel S.S. Warrnambool Master Brodie

TONNAGE:- Built at Superior By whom Sunderland S. B. Co When 1892 YEAR. MONTH.
GROSS 3513 Owners A. Lund Port belonging to London
UNDER DK. 3213 Owners' Address
NET 2213 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? 7 Name of Dock Not India Destined Voyage
WB=CellDBoBBo feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 59147 Port Am
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. Years allowed to expire. Machinery and Boiler Surveys (including date of N.B., if any).
100 A 1 * 2. M.C. 9. 46
8. 97
S.S. Jan - 1. 97.

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition
Hull and bottom examined in dry dock and the bottom cleared and recoated.

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed	✓	✓	✓	✓	✓	✓	✓	✓
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Timbers of Frame at the openings	Rudder	Hatches
Decks <u>Good</u>	<u>Good</u>	<u>Good</u>	<u>Good</u>
Waterways			
Coamings			
Up'r Dk. Beams & Fastenings			
Low'r Dk. Beams & Fastenings			
Plating			
Blanking			
Rivets or Bolts			
Breasthooks & Stemson			
Transoms, Pointers, & Crutches			

General Observations, Opinion as to Class, Recommendation, &c. :-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,97," or "to remain as classed and to have record of survey, 1,97, and the notations of ss No. 1-97 and ptND97, &c."
This vessel is now in good and efficient condition, and eligible to remain as Classed, with record 2. 98.

Office Fee (if chargeable) per Scale II., Sec. 27 £ : : Fees applied for, 18.
Survey Fee (per Section 28) £ : : Received by me, 18.
Special Damage or Repair Fee (if any) (per Sec. 28.) £ : :
Travelling Expenses (if chargeable) £ : :
Second Surveyor's Fee (if any) £ : :

Committee's Minute
Character assigned 100 A 1
TUES. 22 FEB 1898
Surveyor to Lloyd's Register of British & Foreign Shipping.
Lloyd's Register Foundation
LON714-0458

Was a Survey also held on the Machinery of the ship? If so, is the Report sent now, or when will it be sent?

Is Certificate required? If so to be sent to