

Screw shaft examined, stem tube drawn
removed.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD. B & M. S. 3, 9 Subject-

the Monkey Boiler being
again examined & unwound
before the end of Jan 98
Monkey Boiler pressure
to be recorded 40 lbs

LL
12/3/98

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation